American Machinist

[ISSUED WEEKLY]

The International Journal of the Machinery Industries

Volume 71

July 1 to December 31, 1929

McGraw-Hill Publishing Company, Inc.

Tenth Avenue at 36th Street

New York

The Macmillan Publishing Company, Inc.
Third Avenue at 10th Street
New York

620.5 v.71 pt.1

American Machinist

Index to Volume 71

July 1 to December 31, 1929

	Page
July 4	1-36
July 11	37-74
July 18	75-152
July 25	153-188
Aug. 1	189-226
Aug. 8	227-266
Aug. 15	267-304
Aug. 22	305-342
Aug. 29	343-382
Sept. 5	383-420
Sept. 12	421-458
Sept. 19	459-534
Sept. 26	535-572
Oct. 3	573-610
Oct. 10	611-648
Oct. 17	649-686
Oct. 24	687-724
Oct. 31	725-762
Nov. 7	763-800
Nov. 14	801-838
Nov. 21	839-876
Nov. 28	877-914
Dec. 5	915-952
Dec. 12	953-990
Dec. 19	991-1028
Dec. 26	1029-1066

A

Abrasive wheels, angle dresser for, H. Q. Munn ..... ‡710
Abstracts of A.S.M.E. papers....973-982, 990c
Accidents and Accident Prevention:
Eye accidents cost $50,000,000 (ed). 184
In Pullman car shops 345
Mechanical materials handling reduces foundry accidents (ed) 336
Painting, safety guards in red. F. F. Greely 13
Safe dies a necessity in power-press safety. R. A. Shaw. (Abstract of paper at N.S.C.) 741
Safety devices for machinery. Luther D. Burlingame 638
Safety practice for conveyors 843
Adams milling head for planers *564
"Ads," using blind. Theodore Kruger ... 862
Air compressors, Ingersoll-Rand type 30 *1062
Aircraft Construction:
Airplane engines, radial. Frank C. Hudson *444
Design factors of commercial airplanes. Charles T. Porter 975
Heat-treating aircraft engine bearings. J. B. Nealy *1041
Heat-treatment of airplane parts. R. E. Johnstone *389
Metal in, (ed) 216
Metals in. John F. Hardecker. *629
Metal work in building airplanes. R. E. Johnstone *699
"Alive" ball-bearing tailstock center *604
Allen-Bradley bulletin 825 overload breakers *647
Allen-Bradley splash-proof, motor starting switch *838
Allen-Bradley starter *835
Alloys:
Acid-resistant, "Hastelloy" Haynes Stellite 264
Aluminum, for pressure die castings. Sam Tour 28
Chrome-iron, "Rustless" 647
Gray iron, classification of, J. W. Bolton 53
Hardness distribution produced by cold working. W. P. Sykes & A. C. Ellsworth (Abstract of paper at A.S.S.T.) 547
Magnesium and its, W. G. Harvey ... 624
Magnesium comes into its own (ed).. 646
New automotive products at the National Metal Show. Herbert Chase *593
New, in railway rolling stock. Fred H. Colvin *449
Progress in materials, at the Metals Exposition. George S. Brady *551
Service characteristics of light. E. H. Dix, Jr. *441
Welding copper and high-copper. Ira T. Hook. (Abstract of paper at A.W.S.) 595
Alloys. See also Metals.
Aluminum:
Extruded, shapes facilitate design ... *236
In heavy machinery *959
Kettles, spinning & welding heavy gage *22
Screens, design for severe service. E. P. Balch *811
Service characteristics of light alloys. E. H. Dix, Jr. *441
"American" flexible coupling *455
American management (ed) 184
American Railway Foremen's Association:
Annual meeting, Chicago, 1929 .....572c
American Society for Testing Materials:
Atlantic City meeting 36a
Ampco "4-in-1" lathe mandrel *381
Apex floating tap sleeve *794
Apprentices:
Indifference to the apprentice system. Charles E. Dawson.—Discussion. A. W. Forbes 178. H. M. Darling, W. R. Needham 667
Training future diemakers. E. Griffith 1032
Arc Welding. See Welding.
Armor Type C totally-inclosed fan motors *338
Armstrong-Blum No. 8 metal bandsaw ... *187
Assembling Machines:
Intermittent reciprocating movement. P. Zulinski ..... ‡459
Astronomical Instruments:
For studying movements of stars and planets (Zeiss Planetarium) Henry Simon *227, *433, 625
Production operations on the Zeiss Planetarium. Henry Simon ...*737, 897
Automobiles—Manufacture:
Boring 8-cylinder motor blocks *658
Brakes and brake materials *969
Chevrolet-six design based on economics. Alex Taub *241
Chrysler hydraulic brakes. Edward C. Lee *171, *201
Connecting rod methods that are unusual. (Stutz Motor Car) Fred H. Colvin *25
Design of the rail motor car. C. O. Guernsey *973
Dies and tools for four-piece rear axle housings: Chrysler Corporation, Detroit. Frank W. Curtis *915
Enameling fenders for Chrysler cars. E. J. Hunt *267
How many cylinders? (ed) 834
Milling operations on Houdaille shock absorbers. (Ford) Charles M. Reesey *271
Million dollar design research unit, Cadillac Motor Car Co. *808
Monorails—the carryalls in the Studebaker plant *540
Motorcoach design requirements. Dwight E. Austin 960
Oakland heat-treatment control *1036
Oakland motor plant saves $542,000 through war on waste. Ray Chalmers *305
Plymouth crankshafts, set-ups for. Frank W. Curtis *767
Present practice and trends in truck design. B. B. Bachman. (Paper at World Engineering Congress) 825
Recent designs in parts and accessories ‡816
Steering knuckle production at the Studebaker plant. Frank J. Oliver *725
Straight-line production of rear-axle housings. Chrysler Corporation. Frank W. Curtis ..... ‡*351
Studebaker methods of forging and heat-treating. Frank J. Oliver, Jr. *383
Three models on one assembly line. *881
Automotive products at the National Metal Show. Herbert Chase *593
Axes, tempering and coloring. Wirt S. Scott *707

B

Babbitting:
Centrifugal "M.C.E." machines *337
Recovery of waste from. P. J. Potter (Abstract of paper at A.I.M.M.E.) 584
Balancing machine, Losenhausenwerk type S.K.I. *1062
Balancing machines, static and dynamic, "Krupp-Losenhausen." *571
Ball-bearing centers for heavy turning 364
Ball-bearing live center, "Ready" *1065
Ball-bearing tailstock center, "Alive" *604
Ball-testing apparatus, Losenhausenwerk portable *338
Banker or pawnbroker (ed) 1056
Barber-Colman gear hobbing machine *869
Barnes No. 221½ production-type, all-geared, drilling and tapping machine. *679
Barnes No. 242 two-spindle production gang drill *949
Barrels, "Detroit" steel shop, ... *1066
Baush two-spindle nut-driving machine ... *223
Bearings:
Ball, airplane-type, Fafnir S series .. *455
Ball, New Departure, single-row, self-lubricated N-D-Seal *835
Ball, single-row annular, Hoover *456
Cooling hot, W. F. Schaphorst 843
Detecting hot, W. F. Schaphorst 583
Facing, with an air drill. Herbert F. Crawford *598
Grease specifications for use in roller, P. H. Cassidy 929
Heat-treating aircraft engine, J. B. Nealy *1041
Kink in fitting roller, D. A. Hampson ‡31
Oils recommended for well-enclosed ball, P. H. Cassidy 927
Radial, Hyatt single-row *455
Radio used for testing roller..... 1035
Rapid oiler for instrument, G. B. Shaw ‡294
Beatty heavy-duty toggle punches *185
Bellevue Type SV high-temperature electric furnace *799
Belt lacing, "Steelgrip" flexible, ... *1066
Belts, replacing endless. R. H. Kasper... 558
Bench legs and benches, Whitney T-iron *1027
Bending fixture, simple, Charles H. Willey *1051
Bending machine, cold, Smith *567
Binks Hurley spray painting outfit. *379
Black & Decker 6-inch portable bench grinder *381
Blanking, sheet metal, material economy in, W. H. Malliet ..... ‡189
Bliss No. 630 High-production press. *911
Blount all-purpose tool grinder *794
Blount wet tool grinder for tungsten-carbide tools. *951
Blowers, improved by substituting sheet metal for cast iron *247
Blueprinting and Blueprints:
Before the days of, H. S. Ashton 248
Blue-printing machine, "Peerless" model 30 ..... *263
Bolender gear grinding chuck *908
Bonney chrome-vanadium double hexagon sockets and wrenches *875
Boring:
Bar holder for use in lathe. Albert Feucht ..... ‡294
A curved hole. B. H. E. MacLean ..‡182
A curved hole. H. C. Card.—Discussion 673
And turning simultaneously, Clifford H. French *1014
End mill used as, tool. Malcolm K. Parkhurst *1015
Finding clearance for work on, mills. K. Takahashi 1016
Motor blocks, 8-cylinder *658
Simple tools for babbitting and boring connecting rods. Kornschutz ..... ‡30
Tapered hole in locomotive crosshead. Frank J. Oliver, Jr. *785
Machines, jig, Société Genevoise. *376
Machine, and reaming, Defiance two-way opposed, horizontal, ... *950
Machine, wood, reel, Root style "AMR" *1023
Machine, wood, Root style "GM" ..*1027
Machines, Hill horizontal *1061
Boring. See also Drilling.
Boy & Emmes "Coneless" 16-inch lathe ..*677
Bradford three-head drilling and reaming machine *904
Brakes:
And brake materials *969
Chrysler hydraulic, production tools for, Edward C. Lee *171, *201
Reduced manual labor by centralized control of operating mechanisms ...*818
Braun Model SRB radial drilling and tapping machine *874
Braun radial drilling machines *790
Breakers, overload for small motors, Allen-Bradley Bulletin 825 ..... *647
Brisben combination tool holder *35
Browne & Sharpe:
Die holder 419
Gear hobber, No. 31 ..... *379
Micrometer caliper, No. 24 and No. 54 ..... *910, 912
Wire gage selectors, Nos. 698A and 698B 1066
Bryant No. 12 semi-automatic hole grinder *722
Buckets for handling steel shavings. Ralph N. Stryker ..... ‡599
Buda safety self-lowering jacks *605
Buffalo 16-inch sensitive drilling machines *224
Buffalo "Wetboy" unit heater and air conditioner *1062
Buffer, dual-motor Texdrive, Hisey-Wolf, ..*341
Bulldozer, repairing a, O. B. Servel *784
Busch-Sulzer hydraulic molding press *871
Bushings:
Forging tools for locomotive connecting rod, Frank W. Curtis *849
Servicing floating for connecting rods. Frank W. Curtis *323
Business Conditions:
Real values (ed) 946
Business leadership, politico (ed) 986

C

Calendar simplification (ed) 374
Cams, cutting, in a radial drill. W. H. Peach ..... ‡295
Carriage-return, improvised hydraulic. C. D. Michener *711
Casehardening of locomotive parts. Franz Bermann ..... ‡678

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Cast Iron:
High strength. E. J. Lowry 412
Power required to drill, and steel. O. W. Boston and C. J. Oxford 939
Supplanted by sheet metal in fans and blowers .....•247
Casting. See also Die-Casting.
Castings:
Aluminum alloys for pressure die, Sam Tour 28
Aluminum-alloy, heat-treating .....•403
Centering eccentric work accurately. Arthur Fetter 294
Chain, 2½-in. pitch roller, Diamond No. 480 .....•988
Chambersburg 24,000-lb. steam drop hammer .....•948
Chart:
Chart board for the storeroom. Trevor Bonsall—Discussion 553
Chart for selecting substitute stock for forgings. K. Takahashi .....‡831
Chicago overhead-drive gap shear 417
"Chicago" rotary type No. 88 grinder ....•799
Chisel, safety guard for. R. E. Marks ...•748
Chuck, repairing a, N. Kaufmann .....•1054
Chucking Machines:
Apex friction, for electric and air tools •870
Gear grinding, Bolender .....•908
Hydraulic, Cleveland model M, 7-inch, 5-spindle .....•715
Vertical, "Production" .....•791
Cincinnati Brake drum grinder .....•1059
Cincinnati Cutter grinder, No. 2 .....•873
Cincinnati fixture for grinding support blades .....•222
Cincinnati Floor-level hopper for centerless grinders .....•1028
Cincinnati "Hydromatic" milling machines, No. 3-24 plain and duplex .....•1057
Cincinnati "Maxi-Production" lathe .....•792
Cincinnati milling machine, Type M, improved .....•948
Cincinnati milling machines, No. 3 plain, universal and vertical .....•603
Clamp for splicing cable-eyes. C. F. Henry•1053
Clark No. 000 U "Wonder" ¼ in. electric drill .....•875
Cleveland Model M, 7-inch, 5 spindle, hydraulic chucking machine .....•715
Clocks:
Precision in a low-priced product. O. G. Williams ..... •9
Clutch:
Disk, Edgemont Type SF .....•457
Coats Type R-80 elasticometer .....•420
"Cobly" No. 55 metal sawing machine ....•678
Cochrane-Bly improved No. 66 metal-sawing machine .....•797
Cold-heading bolts, relief attachment for. Fred R. Daniels .....•597
Collective thinking (ed) 602
Collets, holder for. Theodore Kruger, 260 Discussion. Arthur F. Parker, ... 863
Communists, best defense against, Harry Kaufman. Discussion 164
Competition, encouraging (ed) 676
Connecting Rods:
And valve tappet guides, finishing. Charles F. Henry .....•712
Machining, without distortion .....•890
Methods that are unusual. Fred H. Colvin •25
Servicing floating bushings for, Frank W. Curtis .....•323
Conradson expanding reamer and arbor •1019
Control Mechanisms:
Hydraulic control mechanism, General Electric .....•836
Photoelectric cell, a mechanical selective device. Edgar H. Felix .....•819
Planer control, General Electric .....•457
"Reco" control device. .....•988
Reversing drum controller, Westinghouse, Type A 185
Time-cycle control units .....•1043
Control (Production):
Centralized, reduces manual labor in operating mechanisms .....•818
Oakland heat-treatment, ...•1036
Convex facing, attachment for. Charles Kugler .....‡713
Conveying and Conveyors:
Arc welding a monorail conveyor. Joseph W. Meadowcroft .....•356
Gravity, facilitates assembly of portable tools .....•1004
Large scale washing of small metal parts. Fred H. Colvin .....•665
Safety practice for, ... 843
Coring:
Core-cutting and coning machine, Wadsworth No. 1 .....•606
Core-making machine, Wadsworth No. 1 .....•566
Cored crown brasses. P. W. Lambert •832
Cost system, making good use of, Harry Kaufman 156
Costs:
Controlling production, in the small shop. E. A. Terrell 649, 691, 733
Cutting, on long push-rods .....•933
Twelve years experience with economic production quantities. C. H. Best 940
Counterbore, spherical. H. L. Wheeler ..‡371
Countershaft, friction driven, "Duro" ....•456
Coupling, "American" flexible .....•455
Crankshafts:
Forging and machining a heavy. James R. Cornelius .....‡745

Page

Repairing a broken. Jim Henderson ‡370
Set-ups for Plymouth. Frank W. Curtis .....•767
Cross gear tooth rounder .....•720
Curtiss-Wright merger joins ten companies 36b
Cutler-Hammer automatic across-the-line starter for D.C. motors .....•989
Cutler-Hammer toggle switch .....•35
Cutter blade holders, O. K. .....•186
Cutter for washout-plug holes. Leonard R. Denst 1015
Gear, on a shaper.—Discussion. J. T. Towlson 747
Head for interchangeable formed cutters. Martin H. Ball. ..... ‡67
Radio tube filaments. Henry C. Franklin .....•369
Round table on metal, (ed) 1018
Saw blades for No. 0 cut-off machine, Ryerson 952
Spiral grooves in thrust washers.....‡334
Threads in tough metals. Arthur F. Parker, 32 Discussion. J. T. Towlson 944
Torch—, steel parts to replace castings. W. J. Buchanan. (Abstract of paper at A.W.S.) 544
Turning with shallow cuts at high speeds. H. J. French and T. G. Digges 935
Wood and fiber, tools for. Charles Kugler .....‡372
Cutting:
Circle cutter for paper templets. L. Coon .....•944
Cylinders, air, self-adjusting, non-rotating Logan .....•380
Czecho-Slovakia, machinery industries in, 420c

D

Davenport universal die-holding stand ....•609
Decentralizing factory districts (ed) 602
Deckel universal tool milling machine ....•302
Defiance No. 613 aluminum airplane propeller turning lathe .....•910
Defiance special 36-in. heavy-duty drilling machine .....•1019
Defiance two-way opposed, horizontal boring and reaming machine .....•950
Defiance valve-hole drilling, reaming counterboring and spot-facing machine •225
Depreciation:
Accounting for, in a period of falling prices. Thomas B. Frank 879
And the associations. (ed) 866
Two methods of calculating. F. Trevor Daniel 702
Design:
American designs abroad (ed) 262
Automotive parts and accessories ...‡816
Calculations, shortening labor in. Alfred Wasbauer .....‡617
Changes that influence sales. (Engineering Council) 238
Conical spring. Joseph Kaye Wood ‡620
Extruded aluminum shapes facilitate •236
Facts first—design afterward (ed) .. 454
Flanged motor mountings on foreign machine tools. Thomas Addison & Herbert Chase .....•611
Hardware .....•965
Improving machine (ed) 34
Incentives for designers (ed) 987
Machine, mechanical motions useful in .....•256
Machine tool, noteworthy progress in 472
Of six-wheel vehicles .....•982
Of Textolite gears. H. D. Randall ..•1033
Present practice and trends in truck. B. B. Bachman (Paper at World Engineering Congress) 825
Railway, parts and equipment.....‡817
Redesign for welded construction. J. M. Robinson .....•249
Roller-bearing spindle mountings. (Ref. Book Sheet) .....•833
Saving time in die. Philip F. Shafran 944
Stub spur gear diameters. (Ref. Book Sheet) 601, 645, 675
Tool, and production, executive consideration. M. H. Flynn.....‡313
Typical oil-hole covers. (Ref. Book Sheet) 985
Unusual progress in, indicated by events in October.....•838a
DeWalt improved "Wonder Worker" saw. .•225
Diamond face grinding machine.....•1058
Diamond No. 480, 2½-in. pitch roller chain •988
Dictation Machines:
Design of the Dictaphone. L. C. Stowell 953
Dictaphone,—a study in intricate mechanism. Theodore H. Beard...•954
Die-holder, Brown & Sharpe.....•419
Die-holding stand, Davenport universal...•609
Die stock, Oster "Leader".....•604
Dies:
And tools for four-piece rear axle housings. Frank W. Curtis.....•915
Danly die sets.....•799
Draft protractor for diemakers. A. Dana Seeds .....‡785
For radius rods.....•861
Hard and half-hard. E. Griffith....•1013
Safe, a necessity in power-press safety. R. A. Shaw. (Abstract of paper at N.S.C.) 741
Seven-stage progressive die. George T. Kerr .....•1051
Split, for press work. R. E. Marks..•784
Sheet-metal blanking. W. H. Malliet.‡189
Standardizing names of die set parts.. 537

Page

Tool work on contract. George S. Brady .....•573
Training future diemakers. E. Griffith.1032
Trimming hardened. John R. Godfrey 4
Typical die sets. (Ref. Book Sheet). 215
Dies, see also Tools
Diesel engine set-up in West Coast plant...•780
"Dimondite" tungsten-carbide cutting metal 683
Disks:
Holding irregular shaped, in a lathe chuck. Fred Ladwig.....‡674
Making brass. H. M. Darling.—Discussion. C. Kugler..... 296
Distribution:
Census of (ed)..... 298
Costs, reducing. Robert F. Elder..... 179
Drafting:
Co-operation between, room and shop. J. A. Potter 45. Discussion. John F. Hardecker 193. J. A. Potter.... 978
Draftsman learns a lesson in the shop. William F. Kunz..... 444
Executive routine of modern, room. Lloyd Y. Squibb. Discussion. J. A. Potter 813
Give the draftsman a chance. Karl Nixon. Discussion. W. R. Needham 258
Laying out an angle without a protractor. Don. R. Hammitt.....•984
Method of cross sectioning. Roy E. Peterson .....‡644
Method of dividing by the use of a scale. Don. R. Hammitt.....‡644
Modernizing the checking squad. Peter Hagen 824
Practical contact for the designer. William F. Kunz 246. Discussion. Morton Schwam 617
Room, blackboard in the. Roy E. Peterson 259. Discussion. W. R. Needham 983
Room, executive routine of a modern. Lloyd Y. Squibb..... 616
Scales, manufacture of. Donald A. Hampson 316
Simple precautions for better drawings 448
Substitute for cross-hatching. Morton Schwam 810
Drafting. See also Drawing.
Drawing:
Aid to checking. Samuel Kaufman...‡643
Boards, repairing. George F. Watt... 644
Desks, Lehigh .....•837
Dimension lines on. Harry Hoisington 250
Keeping a live drawing file. P. H. White 628
Method for checking. Discussion. J. H. Groom 258. W. Mardy..... 425
Method of cross sectioning. L. Coon.‡259
Scale for unscalable drawings. Peter Hagen 983
Standardizing, sizes. Harry Kupper 425. Discussion. Arnold C. White 826
Drawing. See also Blueprinting.
Drawing roll, Rockford.....•947
Drillhead, multiple spindle, Gray "Super".•836
Drills and Drilling:
And tapping machine, production-type, all-geared Barnes No. 221½.....•679
Drilling:
A curved hole. Homer Marion.....•899
Cutting cams in radial drill.....‡295
Deep-hole, job. Hubert E. Redden...•283
Power required to drill cast iron and steel. O. W. Boston and C. J. Oxford 939
Drilling Machines:
"Buffalo" 16-inch sensitive.....•224
Clark No. 000U "Wonder" ¼-in. electric .....•875
Defiance special 36-in. heavy duty..•1019
Electric, ⅝-in. Wodack.....•303
Edlund No. 1A, 24-in. production type.•794
Enterprise station-type .....•221
Gang, Barnes No. 242, special two-spindle production .....•949
Multiple-spindle horizontal, Kent....•223
Radial, and tapping machine, Braun model SRB .....•874
Radial drilling machine, Braun.....•790
"Speedway" Type 59 ¼-inch electric.•798
Thomas multiple, machine.....•570
"Whirlwind" bench-type horizontal..•1024
Driving pin used in a lathe. Frank J. Oliver, Jr. 864
Dunmore No. 5 grinder.....•605
"Durimet" corrosion-resistant steel..... 647
"Duro" friction-driven countershaft.....•456

E

Edgemont Type SF disk clutch.....•457
Edlund No. 1A 24-inch production type drilling machine .....•794
Elasticometer, Coats type R-80.....•420
Electric cords, keeping, off the floor. Van Gilder .....‡333
Elevator, portable, Revolvator "Red Giant" •792
"Elverite" chilled iron..... 264
Emergency repair. C. L. Nadon..... ‡31
Employees:
Art of hiring men. K. Rankin.....1049
Pensions or poorhouses (ed)..... 714
Placing the worker in the right job. Joseph Bell 587
Small loans to..... 12
Small-shop foremen as personnel men. Arthur Mumper—Discussion. R. G. Hewitt 661

(•) Illustrated (‡) Diagram (ed) Editorial

Page

Employment, trend of, in metal working industries 188c 1028c

Enamel and Enameling:
- Of the Plymouth fender, progressive. E. J. Hunt .....•267
- Porcelain, metal parts. P. W. Hopkins .....•49, 167
- Stove parts enameled in modern manner. R. N. Detzer .....•1047

Engineer, who gets the,? (ed) 646

Engineering:
- Co-operation in. H. D. James 448

Engineering Council:
- Design changes that influence sales.. 238
- Developing new products 814
- Do you still "Roll your own"?..... 966
- When sales take a slump 618
- Who should design patterns?..... 430

Engineering terminology (ed) 834
Enterprise station-type drilling machine...•221

Equipment:
- Does college, affect the machine industry? (ed) 298
- In a southern railroad shop. Edward Kornschutz .....•736
- List of items on display at National Machine Tool Builders' Exposition, Cleveland .....•474
- Modernization in 1930 (ed) 866
- Obsolete, should be replaced (ed)...1018
- Semi-annual review of.....•75-151
- What obsolete, costs.....1, 763
- What obsolete, costs. Discussion. Peter A. Brill 331

Ex-Cell-O grinding machine spindles.....•607

Executive Forum:
- Does a highly developed system pay?. 578
- Entertaining—and how much?..... 656
- Equipment replacement in slack periods 882
- Exchanging ideas on shop methods... 158
- Fitting the older worker for his job.. 730
- Friendliness in business..... 538
- Hiring back old men first..... 6
- Holland suggests an engineering council 194
- How long should records be preserved? 1038
- Insuring machines against undue wear 46
- Making a manager out of a foreman.. 844
- Neglecting letters loses an order..... 272
- Night shift 348
- Should a plant take an annual inventory? 998
- Upsetting production schedules..... 696
- What should we teach apprentices?.. 310
- Who should do the estimating?..... 920
- Will it pay to enlarge the plant?..... 770

Extractor for stems of piston valves. H. H. Henson .....‡182

F

Faceplate square. A. Dana Seeds.....•1014
Factories, American branch, abroad. Dr. Julius Klein 687
Fafnir S series airplane type ball bearings.•455
Fans, improved by substituting sheet metal for cast iron .....•247
Farrell-Birmingham metal-forming mill...•565
Fay & Egan No. 575 duoble-arbor universal saw .....•609
Federal Model 36 small hole gage.....•220
Federal No. 33 punch press for large light work .....•606
Fellows improved No. 6A gear shaper....•949
Files, rotary, "Profilo" .....•606
Filter press oil purifier, Westinghouse-Sharples supercentrifuge and.....•1060
"Firthite" mechanically-held tungsten-carbide-tipped tools .....•796

Fits:
- German and Skoda tolerances compared. Dr. George Schlesinger....•887
- Discussion. Earle Buckingham..... 24
- International system of limit gaging. John Gaillard 153, 197, 285

Fixtures:
- Bending, for terminals. Charles H. Willey .....‡711
- Hand-operated fixture for winding conical springs. H. L. Wheeler..... ‡68
- Milling, designs that save time. Frank W. Curtis .....•849
- Milling, with equalizing clamps. D. Bradford .....‡68
- Production lathe, specialized.....•654
- Slewek lock for.....•906
- Universal reaming, for connecting rods. H. W. Morgan .....‡334
- Wire-bending fixture. Charles H. Willey .....‡181
- With equalizing clamps. A. Becker..‡599

Fixtures. See also Jigs and Fixtures.
Flywheel, machining a forged.....•5
Foote Type HGX worm gear speed reducer.•299
Ford Motor Co.—description of the engineering laboratory .....•980
Foreign Manufacture. See Manufacture.
Foreman, small-shop, as personnel man. Arthur Mumper 52

Foreman's Round Table:
- Advising employees about their affairs 930
- Bonus for the ambitious..... 280
- Buying or making special tools?..... 204
- Compulsory membership in the mutual aid 782
- Eating during working hours.....1006
- Ethics of making a change..... 894
- Games at the noon hour..... 320
- Learning from the small shop..... 590
- More ways than one..... 662
- Paying for dependability..... 554
- Radio in the shop..... 14
- Raising the working efficiency..... 742
- Should the workmen share responsibility 369
- Smoking during working hours.....1044
- Tempering general purpose tools.... 404
- What you do, or what you get done?. 664
- When do automatics pay?..... 54
- Who shall be laid off first?..... 858
- "Why some tools fail"..... 168

Forging:
- And machining a heavy crankshaft. James R. Cornelius .....‡745
- Chart for selecting substitute stock for. K. Takahashi .....‡831
- Joints for oil-well tools.....•318
- Locomotive. Lawford H. Fry..... 411
- Studebaker methods of, and heat-treating. Frank J. Oliver, Jr.....•‡383
- Tools for rod bushings. Frank W. Curtis .....•549

Foster-Johnson reamer for railroad motion work .....•719

France:
- Industry affected by labor shortage...342a
- Industry in Alsace.....188a
- Labor shortage in, (ed)..... 216
- Machinery and machine tools in....1066a
- Wage scale and living cost.....226c

Frew automatic No. 2 tapping machine....•716

Furnaces:
- Accurate heat-treating in the small shop. Fred H. Colvin.....•877
- American HB electric.....•419
- Electric conveyor-type, small parts. General Electric Co.....•340
- Electric, for heat-treating aluminum castings. General Electric Co.....•338
- Enameling stove parts in the modern manner. R. N. Detzer.....•1047
- Heat?treating and carburizing, Rockwell inclosed-front .....•301
- High-temperature electric, Bellevue type SV .....•799

G

Gages and Gaging:
- Cylinder, Starrett Junior.....•380
- Federal Model 36 small hole.....•220
- For setting brake lever arms. Charles F. Henry .....•673
- Gage simplifies setting of drill jigs. H. P. Leonard.....•786
- Limit, can international system be established. John Gaillard..153, 197, 285
- Making, to specified tolerances. J. T. Towlson 766
- Piston leak, for pneumatic hammers. P. J. McCullough.....•451
- Quality control and production. Earle Buckingham 937
- Tools for production of "Hartometer" gage. C. R. Ranney.....•1001
- Wire, again. Discussion..... 287
- Wire gage selectors, Brown & Sharpe Nos. 698A and 698B.....•1066

Gallmeyer & Livingston No. 3 surface grinder .....•721
Gardner No. 3-DA double-spindle polishing lathe .....•795
Garvin Timkenized speedbox for No. 1 automatic tapping machine.....•302

Gears and Gearing:
- Bevel gear charts. (Ref. Book Sheet) 183, 261
- Commercial statistics on, (ed)..... 788
- Design of Textolite. H. D. Randall..•1033
- Diameters, stub spur. (Ref. Book Sheet) 601, 645, 675
- Gear geometry. A. H. Candee....‡17, ‡57
- Gear hobber convenient cabinet for the. R. B. Loveland.....•1013
- Hobber. Brown & Sharpe No. 34...•379
- Hobbing machine, Barber-Colman Type B .....•869
- Rougher, four-spindle manufacturing. Gleason .....•717
- Shaper, Fellows improved No. 6A.....•949
- Small meter. Frank J. Oliver, Jr....•841
- 10,000 to 1 reduction motion. W. E. Sykes .....•426
- Tooth rounder, Cross.....•720
- Visualizing stresses in. H. L. Bradford. Discussion. James R. Cornelius 288

General Electric Company:
- Electrode holder, arc-welding.....•186
- Furnace, conveyor-type, small parts heat-treating .....•340
- Furnace for heat-treating aluminum castings .....•338
- Hydraulic control mechanism.....•836
- Magnetic switch, No. CR-7006-D-30..•220
- Planer control apparatus.....•457
- Relay, multi-finger .....•187
- Single-phase, squirrel cage, capacitator motors .....•988
- Switch, magnetic, small capacity oil-immersed .....•341
- Track-type limit switch.....•836

"General" six-torch automatic shape-cutting machine .....•224

Generators:
- Arc welding, "Carbo-O-Flux".....•1060
- Portable acetylene, Milburn.....•381

Page

Germany:
- Machinery and machine tools in....1066a
- Trade Fair at Leipsig, Aug. 25-31...•74c
- Vacuum cleaner manufacture in the Siemens-Schuckert Works. Dr. Hubert Dransfeld .....•923

Gib-key puller. Discussion. J. T. Towlson 674. Gilbert B. Coombs 1053. Carl M. Dinger 1054
Gibb barrel-welding equipment.....•793
Gibb welding-electrode pressure meter....•868
Gleason four-spindle manufacturing gear rougher .....•717
Gray 108-in. rotary grinder.....•1025

Great Britain:
- Industrial conditions 304a
- Machine tool plants share improvement in British industry 36c
- Machinery and machine tools in....1066a

Greenlee four-spindle screw machine.....•789

Grinders:
- Bench, Dumore No. 5.....•605
- Bench, Schauer 1HP.....•377
- Bench 6-inch portable, Black & Decker •381
- Bench, 6-inch Millers Falls Model 66..•381
- Bench, Van Dorn 7-in. .....•868
- Brake drum, Cincinnati improved...•1059
- Cam, semi-automatic hydraulic Landis.•378
- Combination, and lapping machine for tungsten-carbide tools, "Advance"..•947
- Cutter, Cincinnati No. 2.....•873
- Cylinder, Micro Model J.G.....•608
- Die, "Rotor," Rotor Air Tool Co....•339
- Drill, Gallmeyer & Livingston.....•71
- Face grinding machine, Diamond.....•1058
- Floorstand, Hill-Curtis 6- and 8-inch.. •73
- Floorstand, heavy-duty electric, Hammond type WH "Ace".....•683
- Floorstand, heavy-duty, "Rite-Speed"..•723
- Floorstand, "Standard" combination..•876
- Floorstand, "U.S.," with Gibbs V-disk transmission .....•907
- Floorstand, Hisey-Wolf "Multi-Speed" •912
- Hole, Bryant Nos. 3 and 24, (correction) .....•707
- Hole, semi-automatic, Bryant No. 12.•722
- Hoppers for Cincinnati centerless....•1064
- Rotary, "Chicago" No. 88.....•799
- Rotary, Gray 108-in.....•1025
- Surface, Gallmeyer & Livingston No. 3. 721
- Swing-frame, Safety "200 Series"...•796
- Tool grinder, Blount all-purpose.....•794

Grinding:
- Automatic methods applied to. Frank W. Curtis .....•585
- Collars, improvement in. Discussion. C. L. Henry .....‡643
- Fixture, for grinding support blades. Cincinnati Milling Machine Co..... 222
- Work-handling devices bring approach to ideal automatic. J. E. Caster...•325

H

Hacksaw blades. Simonds "Red Streak" high-speed-steel 606
Hammer, steam drop, Chambersburg 24,000-lb. .....•948
Hammers, pneumatic chipping, Ingersoll-Rand high-speed .....•1026
Hammond heavy-duty polishing and buffing lathe .....•907
"Handy Andy" electric hoist.....•718

Hardness:
- Distribution produced by cold working. W. P. Sykes and A. C. Ellsworth (Abstract of paper at A.S.S.T.)... 547

"Hascrome" welding rod..... 219
"Hastelloy" acid-resistant alloys..... 264
Heat-resisting pot, "Niclad"..... 683

Heat-Treatment:
- Accurate heat-treating in the small shop. Fred H. Colvin.....•877
- Airplane parts. R. E. Johnstone.....•389
- Aluminum alloy castings.....•403
- Centralized control of, processes. Fred H. Colvin .....‡•161, 207
- Heat-treating aircraft engine bearings. J. B. Nealy .....•1041
- Heat-treating in a model small plant. Stanley P. Rockwell Co. George S. Brady .....•992
- In a western shop.....•703
- Studebaker methods of forging and heat-treating. Frank J. Oliver, Jr..‡•383

Heater and air conditioner, Buffalo "Wet-boy" .....•1062
Hill horizontal boring machine.....•1061
Hill-Curtis, "Rite speed" polishing and buffing lathe .....•340
Hill-Curtis 6- and 8-inch floorstand grinders •73
Hisey-Wolf dual-motor Texdrive buffer...•341
Hisey-Wolf "Multi-Speed" grinder.....•912

Hoist:
- Chain, Robbins and Myers differential.•905
- Electric "Handy Andy" .....•718
- Electric, indicating "up" and "down." H. E. Eberhardt..... 390

Holmes No. 14 tilted nut tapper.....•609
Hoover single-row annular ball bearings...•456

Hoover, Herbert:
- Move toward peace (ed)..... 336

Hopper, floor-level, for centerless grinders, Cincinnati .....•1028, •1064
Howell "Red band" single-phase motor....•219
Hunter inserted-tooth saw.....•605
Hunter No. 4 metal cutoff saw.....•187
Hyatt single-row radial bearings.....•455
Hydraulic feeds and speeds. A. L. DeLeeuw 774

(•) Illustrated (‡) Diagram (ed) Editorial

I

Page

Illumination. See Light and Lighting.
"Imperial Major" high-speed tool steel... 607
Indicators:
Indicating devices for Reed-Prentice No. 5 jig borer and vertical milling machines .....•791
Photo-electric cell, a mechanical selective device. Edgar H. Felix.....•819
Industry:
American branch factories abroad. Dr. Julius Klein 687
Industrial handicaps (ed) 902
Industrial New England points the way. K. H. Condit.....•1009
Ingersoll-Rand high-speed, pneumatic chipping hammers .....•1026
Ingersoll-Rand Type 30 air compressors..•1062
Inkstand, draftsman's pen-filling, National.•456
Inspector for the shop—why not for the draftsman? J. A. Potter. Discussion. John F. Hardecker..... 27
Instrument manufacture, small machine tools applied to. Frank J. Oliver, Jr. .....•343, •581
Inventories, merry holiday (ed).....1018
Iron:
"Elverite" chilled. Fuller Lehigh Co. 264
Heat-and-abrasive-resistant, "Jewell Alloy" 837
Mayari, characteristics of. (Ref. Book Sheet) 453
Iron. See also Cast Iron.

J

Jacks, Alliance Style 1945 planer .....•790
Jacks, safety self-lowering, Buda .....•605
Jessop "O.K." chisel and steel snap. 564
Jigs and Fixtures:
Jig for drilling drain holes in pistons. Charles C. Tomney 370
Jig plate with adjustable bushing bars. William F. Sandmann ..... ‡67
Quick-lift cams for, G. H. Feltner .... ‡30
Unusual indexing jig. Forrest L. Johnson Discussion 1013
Valve wheels for use on, H. L. Wheeler•900
Joints, forging, for oil-well tools .....•318

K

Kane & Roach No. 3A-18 roll straightener•1021
Kent multiple-spindle horizontal drilling machine .....•223
Kent-Owens high-production milling machine•219
Kent-Owens No. 2 power feed milling machine .....•566
Kerosene burner, "Torit" Type 8-K. ....•1023
Keys, three-piece wedging. I. B. Rich ...‡259
Kimball, Dexter S. Becomes McGraw-Hill director 266a
"Krupp-Losenhausen" static and dynamic balancing machines .....•571

L

"L.M.G." electro-mechanical riveting machines .....•607
Labor:
Art of hiring men. K. Rankin 1049
Difficulties in industrial conscription (ed) 750
Trend of employment in the metal working industries .....188c, 1028c.
Lacquers, insulating and oil-protection, General Electric Co. 71
Landis semi-automatic hydraulic cam grinder .....•378
Lapping machine for air cylinder hammers, "Adjustable" .....•568
Lathes:
Aluminum airplane propeller turning, Defiance No. 613 .....•910
Cincinnati "Maxi-Production" .....•792
"Conelesa" 16-inch engine, Boye & Emmes .....•677
Convex facing in a, E. J. Jordan ....‡372
Miniature turret, used in instrument manufacture. Frank J. Oliver Jr. ‡343, •581
Non-slipping lathe dog. D. Vandercook .....•864
Precision attachment for, Otto A. Wagner .....‡260
Precision, "New Model" toolroom, South Bend .....•217
Preventing damage to, R. H. Kasper.. 674
South Bend "New Model" regular and junior 9-inch. .....•798
Specialized production, fixtures .....•654
"Stub", for brake-drums, Sundstrand.•909
Tool tests, high-speed 157
Turret, Gisholt No. 4 Universal .....•685
Law:
Engineering and patent, recent cases in. Herbert Braasch 354
Laying out angles without a protractor. —Discussion 643
Less said—the better 838c
Lewis-Shepard "Footlift" truck .....•951
Light and Lighting:
Half century of electric, (ed) 714
How about, for next winter (ed) ... 416
How about light for next winter?—Discussion I. L. Kentish-Rankin.. 740
Spacing lights for shop illumination. Louis J. Cahill .....•277
Lighting fixture units, universal parts for sales and service simplification. R. G. Bellezza .....•976
Lincoln gas-engine driven welder .....•380
Lincoln idling device for "Stable Arc" welders .....•1063
Lincoln "New Kathode" welding electrode 222
Lincoln "Stable Arc" welder .....•35
Linestarters, Westinghouse, ...•418, •989
Locomotives:
Locomotive forgings. Lawford H. Fry 411
Locomotive mover, electric, Whiting .....•719
New alloys in railway rolling stock. Fred H. Colvin .....•449
Selective casehardening of locomotive parts. Franz Bermann 673
Servicing floating bushings for connecting rods. Frank W. Curtis ....•323
Logan self-adjusting non-rotating air cylinders .....•380
Losenhausenwerk turning-tool pressure measuring device .....•300
Losenhausenwerk Type S.K.I. balancing machine .....•1062
Lubrication:
Centralized lubricating systems. Herbert Chase .....‡801
"Cosmolubrics" and Houghton absorbed oils 564
Cutting lubricant 881
Lubricating mechanisms. Allen F. Brewer .....•421
Of air compressors 942
Oil and grease, when and where each should be used. P. F. Cassidy 927
Oil filtration on machine tools. Allen F. Brewer .....‡•165
Oiler, rapid, for instrument bearings. G. B. Shaw .....‡294

M

"M.C.E." centrifugal babbitting machines..•337
Machinery:
Aluminum in heavy .....•959
And machine tools in France, Germany and Great Britain 1066a
And the electorate (ed) 562
Employment shows slight decrease..1066c
First in U. S. exports during 1929..914b
Industry, some curious notions about the. Ernest F. DuBrul..... 557
Inspiration of (ed) 454
"Machines in the age to come" (ed).. 454
Textile machines and parts.....•964
Machinery and Equipment Associations:
Fourth conference, at Washington....876c
Magnesium and its alloys. W. G. Harvey.. 624
Management:
Business ethics. (Ref. Book Sheet).. 865
Employee retirement adjustments. (Ref. Book Sheet) 373
Formulas for economic lot sizes. (Ref. Book Sheet) 749
Mandrel:
Indexing, for main-rod brasses. H. H. Henson .....•863
Lathe, Ampco "4-in-1." .....•381
Self-locking. Ernest Foldvary 1016
Manufacturers:
Of American equipment..... 126
Of European equipment 151
Manufacturing:
American branch factories abroad. Dr. Julius Klein 687
Ancient manufacturing. Dexter S. Kimball .....•922
Controlling manufacture by economic lot sizes. Fairfield E. Raymond. (Abstract of paper at S.A.E.) 669
Mass Production:
Precision in a low-priced product. O. G. Williams ..... •9
Materials:
Carbon tool steel, behavior on quenching. G. V. Luerssen 407
Cast iron, high strength. E. J. Lowry 412
Characteristics of (Ref. Book Sheet).. 335
Characteristics of "Hy-ten-sl" bronze. (Ref. Book Sheet) 561
Chisel and snap steel, Jessop "O.K.".. 564
Chrome molybdenum, steel in aircraft construction. R. E. Johnstone....•389
Die steel, Jessop "Albor." 608
"Ermalite" high-strength wear-resistant cast iron 988
Iron, high-permeability "Swedelec"... 647
Molded products that replace metals. H. D. Randall .....•251, •639
Steel, cold-heading die, "Vasco" 566
Steel, corrosion-resistant "Durimet".. 647
Steel high-speed tool, "Imperial Major" 607
Supplying, on time through advance planning. F. M. A'Hearn. (Abstract of paper at I.R.F.A.) 671
Materials Handling:
Devices for handling driving-wheel tires. Henry H. Henson.....•900
Enameling stove parts in the modern manner. R. N. Detzer .....•1047
Handling bar stock and sheet metal. J. S. Browne .....•1053
Mechanical handling of screw machine parts. George S. Brady .....•175
Mechanical, reduces foundry accidents (ed) 336
Modernizing the factory handling system. George E. Hagemann .....•852
Multiplying manpower by the industrial truck .....•274
Measuring Devices:
Measuring internal threads 926
Methods of measuring odd-fluted taps. (Ref. Book Sheet) 945
Micrometer caliper, Brown & Sharpe No. 24, No. 54 .....•910, 912
Transit, measuring within 0.004 in. with a, Discussion. E. J. Jordan..‡786
Turning-tool pressure. Losenhausenwerk .....•300
Vernier caliper, trammel attachments for. Roscoe B. Boone .....‡369
Measuring Devices. See also Gages.
Mechanism:
Intricate—the Dictaphone. Theodore H. Beard .....•954
Mechanization, increasing factory output by .....•856
Men over forty-five. L. C. Newton. Discussion, A. W. Ainsworth..... 157
Metal Cutting. See Cutting.
Metal-forming mill, Farrell-Birmingham..•565
Metal Working:
Industry's operations in 1929 parallel in first and last quarters. R. M. Davis 876a
Metal work in building airplanes. R. E. Johnstone .....•899
Metals:
Chromium 963
Effect of tin, lead and zinc on bearing bronzes 203
In aircraft construction. John F. Hardecker .....•629
Machinability of. (Ref. Book Sheet).. 415
Non-ferrous scrap, reclaiming. Francis N. Flynn. (Abstract of paper at A.I.M.M.E.) 546
Platinum-group, in product design. Frederick E. Carter .....•822
Replaced by molded products. H. D. Randall .....•251, •639
Study of tin-base bearing. G. B. Karelitz and O. W. Ellis 1003
Metals. See also Alloys and names of individual metals.
Micro Model J. G. cylinder grinder.....•608
Micrometers:
Comparator for inside. George C. Warren .....‡598
Repairing. A. J. Wormwood .....‡599
Milburn portable acetylene generator.....•381
Milling:
Fixture designs that save time. Frank W. Curtis .....•849
Portable miller for pedestal toes. R. B. Loveland .....•295
Operations on Houdaille shock absorbers. Charles M. Reesey.....•271
Spline milling spindle design. Fred A. Firnhaber .....•961
Steering knuckles. R. M. Charles....‡333
Success overcomes objections (ed)... 374
Milling Heads:
For planers. Adams .....•564
4½ in. unit. Putnam ..... •72
Milling Machines:
Cincinnati improved type M.....•948
Double-spindle cam, Producto No. 11D.•218
High-production. Kent-Owens .....•219
Kent-Owens No. 2 power feed.....•566
Oesterlein No. 36 "Mil-o-matic."....•684
Plain and duplex, Cincinnati No. 3-24 "Hydromatic" .....•1057
Plain, universal and vertical Cincinnati No. 3 .....•603
Planer-type, 72-inch. Sellers.....•375
Tool, Deckel universal .....•302
Twin-unit machines, for multiple production. F. H. Mayoh .....•289
Minster screw or tryout press.....•1065
Mitchell No. 17 motor-driven polishing lathe .....•950
Molding:
Molded products that replace metals. H. D. Randall .....•251, •639
Platens, Trent electrically-heated....•722
Molybdenum steel, Chrome-molybdenum, in aircraft construction. R. E. Johnstone .....•389
Money Rates:
Witch of Wall Street (ed) 750
Monorails—the carryalls at the Studebaker plant .....•540
"Monotron" for hardness testing.....•297
Morse No. 678 diemakers reamers.....•680
Morton direct-connected reversing drive unit .....•1063
Morton variable-speed transmission.....•1061
Motions, Mechanical:
Mechanical movements useful in design .....•979
Mechanism for producing straight-line .....•84, •256

(•) Illustrated (‡) Diagram (ed) Editorial

Motor Cleaner: Page
Air, Paasche *340
Motor mountings, flanged, on foreign machine tools. Thomas Addison & Herbert Chase *611
Motors:
Adjustable-speed vs. multi-speed a.c., for machine tools. C. E. L. Dapprich *633
Built-in switch, Reynolds Type "C" .. *381
Fan-cooled, Armor Type C, totally inclosed *338
Flanged motor mountings on foreign machine tools. Thomas Addison & Herbert Chase *611
High-frequency, for portable tools. C. B. Coates 450
Interchangeability with flanged (ed). 646
Motor operation on the West Coast .. *918
Single-phase, Howell "Red band" *219
Single-phase, squirrel-cage, capacitator, General Electric type KC *988
"Uniclosed" U. S. Electrical Mfg. Co.. *337
"Multimechanic" multiple-operations machine. Simplex *903
Mycalex—a machinable insulation. W. W. Brown 963

N

National Business Survey Conference:
Personnel of temporary executive committee 1028a
National Conference of Safety Experts:
Convention at Chicago 648a
National Machine Tool Builders Association:
Adopt standard color ..... 266a (ed) 298
Officers elected *762a
National Machine Tool Builders' Exposition:
Cleveland Sept. 30-Oct. 4. Exhibitors, products representatives 460, 648a
Entertainment or information at Cleveland? (ed) 562
Index of machines, and manufacturers. 533
List of items on display at Cleveland. *474
National Machine Tool Congress:
Program, Cleveland, Sept. 30-Oct. 4.. 459
National Metal Congress:
Program of sessions; list of exhibitors 391
"National" wall chart of drill and tap sizes. 724
New England, industrial, points the way. K. H. Condit *1009
New Rockford adjustable bed press, No. 24R *1022
"New Rockford" No. 5 double-crank press *905, *906
"New Rockford" 250-ton knuckle-joint embossing press *1020
N. Y. Stock Exchange—growing pains (ed). 788
Niagara No. 14-M heavy-duty mill squaring shears *1022
Niagara Nos. 54 and 56 single-crank power presses *341
Niagara No. 172 electric combination machine *680
Notcher, Whitney No. 49 ..... *913
Nut-driving machine, Baush two-spindle.. *223
Nut tapper, Holmes No. 14, tilted..... *609

O

O. K. cutter blade holders *186
Obsolescence:
A cue from Washington (ed)..... 902
Insurance company, wanted—an. Gorton James 839
Oil-hole covers, typical. (Ref. Book Sheet) 985
Oliver No. 192 bandsawing machine..... *382
Orders, two reasons for placing, now (ed) 1056
Oven heaters, coke fired core. Young Brothers *908
"Oxweld" No. 21 high-strength welding rod 571
Oxweld Types CLP-2 & CLP-3 acetylene generator trucks *220
Obituaries:
Anderson, Oscar L. 990g
Austerberry, Joseph C. 876g
Baird, Edward P. 876g
Baker, Charles W. 952g
Bassett, George M. 914g
Bayley, Harry F. 610g
Baylor, Armistead K. 266e
Beers, Frederick L. 914g
Beliavsky, Serge 420g
Bindley, Edward H. 36i
Bird, John Dudley 1028g
Bishop, Frederick Lee 762g
Botwinik, Harris 188i
Bowen, Thomas D. 648g
Budlong, Irving J. 188i
Burns, Robert 876g
Carey, William B. 876g
Carroll, Thomas A. 914g
Case, John D. 188i
Chaffee, George T. 188i
Clark, Wallace S. 762g
Coles, Henry Aylett 876g
Cook, Magnus C. 990g
Cowles, Alfred H. 342g
Craft, Edward Beach 458g
Crain, Clarence R. 876g
Cushman, Richard 876g
Darling, John William 304g
Davis, Edward S. 36i
Davis, Hiram M. 572g
Doelger, Charles H. 36i
Drinker, W. W. 648g
Duffke, Louis 952g
Emmet, Richard Stockton 534e
Estep, H. Cole 648g
Fay, Thomas J. 952g
Feltes, John 266e
Fish, Walter E. 534e
Frisbie, Edward L. 74g
Gardner, J. M. 686g
Gilbert, George W. 686g
Golding, John French 990g
Graf, Carl H. 686g
Gundlach, John P. 952g
Hammele, Joseph 152a
Hanson, John Morrison 1066g
Harder, Ernest F. 724g
Harmon, William T. 226g
Harvey, George G. 990g
Hedges, Mertland McClain 342g
Hegewald, Arthur F. 800g
Hemler, Arthur Frisbee 152a
Hendry, John 686g
Hickman, Frank 36i
Hill, George C. 648g
Hill, Henry J. 724g
Hill, Nathaniel P. 266e
Hoffman, Allan 266e
Hollerith, Herman 914g
Hollinger, J. H. 952g
Hood, Chas. A. 914g
Hornung, George G. 1066g
Howe, Thomas F. 610g
Hubinger, Joseph E. 304g
Hunter, Frank A. Sr. 952g
Hurley, John David 534e
Huston, Joseph E. 610g
Huston, Robert T. 1028g
Jackson, Capt. Wm. M. S. 572g
Jenninga, Robert Emmet 876g
Johnson, George M. 610g
Johnson, Homar L. 648g
Jones, Edward T. 458g
Klausmeyer, David C. *990g
Koenig, John 914g
Kroger, Clem H. 952g
Lane, William Henry 226g
Leslie, Forrester B. 952g
McCordio, Alfred E. 458g
McGrath, Ray P. 572g
McKaig, Donald 990g
MacDonald, William A. 36i
Mahar, Franklin W. 188i
Maher, Nicholas D. 610g
Marchetti, Paul 534e
Markowitz, Herman 188i
Mathewson, Alfred Eugene 304g
Mehl, Walter B. 762g
Mesta, Jacob E. 1066g
Miller, David 1066g
Mills, Col. Abraham G. 420g
Milmine, Henry W. 876g
Moore, Chas. B. 914g
Murphy, John Henry 382e
Murray, T. E. 226g
Newbegin, Edward 342g
Newman, Nicholas 420g
Oudin, Maurice A. 1028g
Piepho, E. Byron 74g
Poor, Frederic H. 188i
Price, Fred 990g
Rea, William H. 1066g
Reed, Robert W. 36i
Rice, Nathaniel Montgomery 534e
Rindge, Fred H. Jr. 572g
Ross, James A. 610g
Salmon, Charles R. 762g
Schneider, J. P. 36i
Schroder, Charles H. 304g
Schuhl, Alexander L. 800g
Sellers, Howard 724g
Severson, George W. 1028g
Shants, G. T. 686g
Smallwood, George Thomas 534e
Solomon, Frank 800g
Stone, Charles M. 152a
Sternberg, William 876g
Stevens, John A. 990g
Strauss, William O. 382e
Theobald, John J. 420g
Thompson, Alexander Montgomery 762g
Thomson, George W. 458g
Timble, G. Arthur 990g
Titus, Frederic W. 382e
Trench, C. S. 876g
Turner, John S. 188i
Tyner, Richard H. 876g
Upson, William C. 648g
Van Schaack, David 914g
Vaughan, Louis 610g
Walsh, Charles E. 648g
Wasson, David Clay 610g
Wearden, Louis 304g
Wheeler, David Clark 648g
White, Walter C. 648g
Wickwire, Frederick R. 610g
Willoughby, Horace 686g
Windsor, Walter A. 572g
Winship, Charles R. 762g
Wolff, Eric 990g
Woodrow, O. B. 876g
Worcester, Edward 458g
Wright, Owen S. 648g
Yates, William 188i

P

Paasche air motor cleaner *340
Paasche Type F532 "Explosion proof" ventilating unit *1020
Paint Sprayer: Page
Binks Hurley, outfit *379
Portable electric, Breuer "Tornado".. *909
Parts:
Keeping, readily accessible. Fred H. Colvin *878
Mechanical handling of screw machine. George S. Brady *175
Textile machines and *964
Universal, for street lighting fixtures. R. G. Bellezza *976
Patent Law. See Law.
Patents:
How, fit into sales strategy. H. A. Toulmin, Jr. 363
Lure of (ed) 70
Patent ethics (ed) 750
"Peerless" Model 30 blue-printing machine *263
Peerless vertical heavy-duty sawing machine *720
Pels regulated-pressure eccentric press.... *419
Photoelectric Cells:
Mechanical selective device. Edgar H. Felix *819
Pinion puller, effective. Edward Kornschutz ..... ‡372
Pins, eliminating, for locating purposes. Charles Kugler ..... ‡644
Piston rings, steel. John R. Godfrey; discussion J. T. Towlson 390
Pittsburgh direct-reading, Brinell hardness testing machine *418
Planetarium:
Design of the Zeiss. Henry Simon.. *227, *433, 625
Production operations on the Zeiss. Henry Simon *737
Zeiss—an engineering problem. Erratum 746
Plating:
Equipment, economies with automatic. Floyd T. Taylor *535
Wanted—satisfactory tests for cadmium. Karl A. Eckhardt 995
Platinum. See Metals.
Polishing and Buffing:
Care and cleanliness real assets in. Fred H. Colvin *847
Polishing-wheel, resurfacing machine, Scovil *682
Standard "Right Speed" two motor, machine *304
Porter-Cable "Take-about" type B-7 sander. *913
Pot, tinning, Trent *337
Pratt & Whitney No. 2 six-station vertical automatic *867
President's message (ed) 987
Press:
Adjustable bed, New Rockford No. 24 R. *1022
Bending small parts in hand. C. H. Willey ..... ‡31
Double-crank, "New Rockford" No. 5 *905, 906
Filter, oil purifier, Westinghouse Sharples, supercentrifuge *1060
High-production, Bliss No. 630 ..... *911
Hydraulic, for railroad shop use. I. B. Rich *711
Hydraulic molding, Busch-Sulzer.... *871
Hydraulic, used for assembling chains for tractor treads. Herbert F. Crawford *295
Knuckle-joint embossing, "New Rockford" 250-ton *1020
Mandrel, home-made. Paul Leo..... ‡296
Pels regulated-pressure eccentric..... *419
Printing, attachment for relieving cylinders. George H. Feltner..... *66
Progressive forming punch and die. Ernest Foldvary *1052
Punch, for large light work, Federal No. 33 ..... *606
Punch, in a railroad shop..... *772
Punch, Williams-White improved series *186
Safety guards for punch, Wiesman... *795
Safety guard for punch, treadles. P. G. Dennison *181
Single-crank power, Niagara Nos. 54 and 56 ..... *341
Tryout, or screw, Minster..... *1065
"Product Engineering" (ed) 986
Production:
Controlling manufacture by economic lot sizes. Fairfield E. Raymond. (Abstract of paper at S.A.E.)... 669
Economic, quantities, twelve years' experience with. C. H. Best 940
Formulas for economic, lot sizes. (Ref. Book Sheet), 749; Correction 1054
Gages and quality control. Earle Buckingham 937
Increasing factory output by mechanization *856
Mechanical handling of screw-machine parts. George S. Brady *175
Methods, changing from jobbing to. Arthur Mumper ..... ‡746
Methods in the railroad shop. A. E. Iveson. (Abstract of paper at I.R.G.F.A.) 672
Of track parts for caterpillar tractors. Frank W. Curtis *1029
Quantity, in job shop. Frank W. Curtis *61
Straight-line, of rear-axle housings. Frank W. Curtis ..... ‡*351

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Trends, in standardized quality. John H. Van Deventer. (Abstract from World Congress paper) 777
Twin-unit machines for multiple-, F. H. Mayoh *289
Vacuum cleaner manufacture in the Siemens-Schuckert Works. Dr. Hubert Dransfeld *923
Producto No. 11D double-spindle cam milling machine *218

Pumps:
Gear, lubricating mechanisms. Allen F. Brewer *421
Lubricant, Tuthill *457

Punches:
Rocking-cam driven, for radial holes. Clifford H. French *747
Toggle, Beatty heavy-duty *185
Turret, "Eda," Wiedermann Co.....*302
Punches. See also Presses.
Putnam 4¼-inch unit milling head..... *72

Pyrometer:
Potentiometer-type recording, Wilson-Maeulen Model 8201 .....*870
"Pyroversum," optical *418

Q

Quenching:
Carbon tool steel, behavior on. G. V. Luerssen 407
Hot solutions for, steels. H. J. French and T. E. Hamill 413
Tank agitator, Rockwell *790

R

Rack for heavy stock. Rowland L. Hill..‡598
Rack for storing steel plates. H. P. Leonard *1054
"Raco" packaged welding rod *605
Radial Drill and Drilling. See Drills and Drilling.

Railroads:
Can now order tools (ed)..... 714
Crosshead slipper practice at the C. & N. W. shops. Frank J. Oliver, Jr. *941
Equipment for the car repair shop. E. S. Behen, G. Reichert, and J. T. Jones. (Abstract of paper at A.R.T.F.A.) 545
Equipment in a southern railroad shop. Edward Kornschutz *736
Modern railroad toolroom.....*669
Production methods in the railroad shop. A. E. Iveson. (Abstract of paper at I.R.G.F.A.)..... 672
Punch press in a railroad shop.....*772
Recent designs in parts and equipment..‡817
Shop equipment, Atchison, Topeka & Santa Fe system.....*346
Storeroom, good housekeeping in. C. B. Lord *43
Superheater-unit repair equipment, in shops of the Atchison, Topeka & Santa Fe *588
Super-heater unit repairs in the Chicago and Northwestern shops. Frank J. Oliver *732
Supplying materials on time through advance planning. F. M. A'Hearn.. 671
Ray Type CSB-B electric screw driver....*1024

Reamers and Reaming:
Conradson expanding reamer and arbor *1019
Curved hole. R. W. Buettner.....†66
Diemakers, Morse No. 678.....*680
Factors that increase, life. Herbert M. Darling 12
For railroad motion work. Foster-Johnson *719
Three-head drilling and, machine, Bradford *904
Reed-Prentice indicating devices for No. 5 jig borer and vertical milling machine *791
Reference Book Sheets..33, 69, 183, 215, 261, 297, 335, 373, 415, 453, 561, 601, 645, 675, 713, 749, 787, 833, 865, 901, 945, 985, 1017, 1055
Relay, multi-finger, General Electric.....*187
Research, two kinds of (ed)..... 987
Reversing drive unit, Morton direct-connected *1063
Revolvator "Red Giant" portable elevator..*792
Reynolds Type "C" built-in switch motor *381
Rickert-Shafer semi-automatic tapping machine *303

Rivets and Riveting:
Block simplifies cold. Frank J. Oliver, Jr. *943
Electro-mechanical, machine "L.M.G." *607
Pneumatic dolly for flexible staybolts. George Bexton *943
Rivet-setting machines, "Tubular" automatic *911
Rotary rivet spinning machine, Linley No. 30 D.....*1024
Screws vs. rivets. Charles H. Willey 259
Robbins & Myers differential chain hoist..*905
Rockford drawing roll.....*947
Rockwell inclosed-front heat-treating and carburizing furnaces *301
Rockwell quenching tank agitator.....*790

Page

Rods:
Cutting costs on long push.....*933
Straightening tapered (Shop Problem) 600
Rods. See also Connecting Rods.
Roll straightener, Kane & Roach No. 3A-18 .....*1021
Rollers for flanging tubes. Charles B. Irmer .....†370
Rolling rings, fixture for. Charles B. Irmer †293
Root Style "AMR" reel borer.....*1023
Root Style "GM" wood boring machine...*1027
Ross improved operating valve.....*1063
"Rotomatic" No. 3 continuous pipe-threading machine *569

Russia:
Soviet farm problem (ed)..... 676
Two American clock factories bought by 572b
"Rustless" chrome-iron alloys..... 647

Rustproofing Processes:
Parkerizing, sherardizing, and calorizing. (Ref. Book Sheet)..... 713
Ryerson saw blades for the No. 0 cut-off machine 952

S

Sales:
Design changes that influence (Engineering Council) 238
Is the engineer sales conscious? (ed) 834
Prosperity and installment selling (ed) 70
Salesmanship from purchasing agent's viewpoint. Charles B. Irmer.....1050
Sander, Porter-Cable Type B-7 "Take-About." *913

Saws and Sawing:
Bandsaw, improved safety, Horn.....*682
Bandsawing machine, Oliver No. 192 *382
"Best Bet" hacksaw type tool.....*1061
Cochrane-Bly improved No. 66 metal-sawing machine *797
DeWalt improved Model D, "Wonder-worker" *225
Double-arbor universal, Fay & Egan No. 575 .....*609
Electric, heavy-duty Skilsaw Model R *724
Hunter inserted-tooth *605
Metal bandsaw, Armstrong-Blum No. 8 .....*187
Metal cutoff, Hunter No. 4.....*187
Metal sawing machine, "Cobly" No. 55 .....*678
Vertical heavy-duty metal sawing machine, Peerless *720
Schauer 1-HP bench grinder.....*377
Screens, aluminum. E. P. Balch.....*811

Screw-Machine:
Automatic, Greenlee four-spindle.....*789
Parts, mechanical handling of. George S. Brady *175
Screw stock, cold-finished high-manganese. Ryerson 563

Screws:
Rivets vs. Charles H. Willey.....†259
Screwdriver and nut setter, Strand power *1021
Screw driving machine, Ray Type CSB-B, electric *1024
Scribe block for toolmakers. Charles Doescher .....‡332
Seen and Heard. John R. Godfrey..4, 107, 200, 279, 368, 537, 587, 690, 848, 917
Sellers planer-type 72-inch milling machine *375

Shafts:
Design of, for strength (Ref. Book Sheet) 33, 69
Shape-cutting machine, automatic "General" six-torch *224

Shaper:
Planer, hydraulic, Rockford.....*681
Work problem in. James Henderson.‡294
"Workace" electric, for pattern shops. Wallace Co. *225

Shears and Shearing:
Bar and billet, Smith model 76.....*563
Mill squaring, Niagara No. 14-M heavy-duty *1022
Overhead-drive gap *417
Sheath wire, new product for heating elements. F. E. Findlayson.....*445

Sheet Metal:
Blanking, material economy in. W. H. Malliet .....‡189
Electric combination machine, Niagara No. 172 .....*680
Supplants cast iron in fans and blowers *247

Shops:
Heat-treating in a model small plant. Stanley P. Rockwell Co. George S. Brady *992
Inspector for the shop, why not for the draftsman? J. A. Potter. Discussion, John F. Hardecker..... 27
Tool and die: tool work on contract. George S. Brady.....*573
Simonds "Red Streak" high-speed-steel hacksaw blades 606
"Simplex" pipe vise *304
"Simplex" swivel backjaw vise.....*913
Slippers and guides, practice with crosshead, at C.&N.W. shops. Frank J. Oliver, Jr. *941

Slot:
What is a.? E. R. Plaisted. Discussion. A. J. Black..... 63
What is a. L. O. Brown. Discussion 324

Page

Smith cold bending machine.....*567
Smith Model 76 bar and billet shears.....*563
Sockets and wrenches, Bonney chrome-vanadium double-hexagon *875
Société Genevoise jig boring machines....*376

Soldering:
Soft, underlying principles of. Ripley.‡365

South America:
Buyer of machinery in 1928..... 36g
Industrial development in. Paul Wooton 226a
South Bend "New Model" regular and junior 9-inch lathe *798
South Bend "New Model" toolroom precision lathe *217
Speedbox, "Garvin," Timkenized for No. 1 automatic tapping machine.....*302
Speed reducer, worm gear, Foote Type HGX *299
Spindle mountings, roller-bearing. (Ref. Book Sheet) *833
Spindles, grinding machine, Ex-Cell-O.....*607
Spinning heavy gage aluminum kettle.... *22

Springs:
Conical, design of. Joseph Kaye Wood ‡620
Conical spring design. Joseph Kaye Wood .....‡620
Flexible couplings. Malcolm K. Parkhurst *832
Production of, on a large scale, at Studebaker plant *884
Variable-pitch helical. Joseph Kaye Wood .....‡827
"Square D" combination starter.....*221
"Standard" combination grinder.....*876
Standard "Right speed" two-motor buffing and polishing machines.....*304

Standardization:
Plumb bobs and (ed)..... 788
Progress in, procedure (ed)..... 374
Unwise, and specifications (ed)..... 336
Starrett Junior cylinder gage.....*380

Starter:
Allen-Bradley, with disconnect switches and meter test jacks.....*835
Automatic across-the-line for D. C. motors. Cutler-Hammer *989
Combination "Square D".....*221

Statistics:
Exports of industrial machinery, 1929 .....1028a
Metal-working industry, third quarter 1929. Robert M. Davis.....304b
Metal-working plants, operations.....188b
30 per cent increase in manufacture of airplanes and parts in year....382a
Time for business (ed)..... 946
Volume of metal working operations 724b
Wage earners in metal processing industry 420b

Steel:
Arc-welded construction, redesign for. J. M. Robinson.....*249
Carbon tool, behavior on quenching. G. V. Luerssen..... 407
Power required to drill and cast iron. O. W. Boston and C. J. Oxford.... 939
Steering knuckle production at the Studebaker plant. Frank J. Oliver.....*725
Strand power screwdriver and nut setter..*1021
Stress, factor of safety and working. C. Richard Soderberg 1000
Sundstrand "Stub" lathes for brake-drums *909
Swaging machine, improvised. H. B. Loveland *371
"Swedelec" high-permeability iron..... 647

Switches:
Automatic, two spindle speed.....*317
Field discharge, for magnetic chucks. Taft-Peirce *456
Magnetic, General Electric, No. CR-7006-D-30 .....*220
Oil-immersed, small capacity magnetic, General Electric Co.....*341
Rubber-mounted, toggle *35
Splash-proof, motor starting, Allen-Bradley *838
Taft-Peirce field discharge, for magnetic chucks *456
Track-type limit, General Electric...*836

T

Tap sleeve, Apex floating.....*794
Taper socket, knockout plug for. H. L. Wheeler .....‡294
Tapers, do we need thirty-eight? (Table arranged according to d'ameters). Fred H. Colvin 831

Tapping:
Fixture, an efficient. H. M. Darling †600
Machine, Braun model SRB.....*874
Machine, Frew No. 2 automatic....*716
Machine, production-type, all-geared, Barnes No. 221½.....*679
Machine, semi-automatic Rickert-Schafer *303

Tariff:
Annoys business (ed)..... 714
Red herrings (ed)..... 602
Tariff education (ed)..... 184
Taxation—a sore spot (ed)..... 902
Tempering and coloring axes. Wirt S. Scott *707
Terminals, tight, for meters. C. H. Willey 984

Testing and Tests:
Hardness-testing machine, Pittsburg direct-reading *418

(*) Illustrated (‡) Diagram (ed) Editorial

Page

High-speed lathe-tool 157
Insuring weld reliability by testing welders. Paul Orr ..... ‡*329
Methods of hardness testing; the Monotron (Ref. Book Sheet) *297
U. S. Standards Bureau evolves new, for lathe tools 914b
Wanted — satisfactory, for cadmium plating. Karl A. Eckhardt 995
Textile machines and parts *964
Thomas multiple drilling machine *570

Thomson:

Welder, Model 290, heavy-duty power driven vertical *299
Welder, Model 375 heavy-duty double-roller seam *339
Welder, No. 5 Special *71
Welder, Series 180 spot *73
"Thor," No. 278 pneumatic wrench *951
Thread button set, National "Make-Shur" *686

Threading:

Device for controlling movements of threading tools. E. H. Fader ..... †32
Emergency method of thread calculation. Peter Hagen 632
Pipe, machine "Rotomatic" continuous *569
Time-cycle control units *1043

Tolerances:

German and Skoda, compared. Discussion. Earle Buckingham, 24; Dr. George Schlesinger *887
Making gages to specified. J. T. Towlson 766
Quality control and production gages. Earle Buckingham 937
Toolbit, high-cobalt Simonds 565
Toolblocks, repairing T-slots in. Charles Kugler 900
Tool grinder, Blount wet, for tungsten-carbide tools *951

Toolholders:

Apex floating *567
Brisben combination *35
For planer, special. H. F. Fiedler ..... ‡333
Toolroom, is the, passing George A. Greetham 917

Tools:

Air-operated, in a railroad shop. R. E. Marks *1052
And dies for four-piece rear axle housings. Frank W. Curtis *915
Congestion at the machine. J. T. Saville. Discussion, R. G. Hewitt .. 210
Design and production, executive considerations. M. H. Flynn ..... ‡*313
Flanged motor mountings on foreign machine. Thomas Addison and Herbert Chase *611
For babbitting and boring connecting rods. E. F. Kornschutz 30
For piercing walls of ammeter cases. Charles H. Willey ..... ‡332
For production of "Hartometer" gage. C. R. Ranney *1001
For small-lot production of brass parts. Arthur V. O'Brien *659
Grinding of Carboloy 355
High-speed lathe tests 157
"Kant slip" plier *905
Keeping a line on. Frank V. Faulhaber 840
Machine, motors for. C. E. L. Dapprich *633
Machine, oil filtration on. Allen F. Brewer ..... ‡*165
Machine tool industry, selling, to students (ed) 34
Mechanically - held tungsten - carbide - tipped, "Firthite" *796
Methods of measuring odd-fluted taps. (Ref. Book Sheet) 945
Multi - bladed screwdriver. Samuel Kauffman *864
Oil-well, forging joints for *318
Production, for Chrysler hydraulic brakes. Edward C. Lee *171, *201
Putting-on tool. J. T. Towlson. Discussion 1035
Small machine, applied to instrument manufacture. Frank J. Oliver, Jr. ..... †*343, 581
Stud setter, Titan quick-release *912

Page

Tool work on contract. George S. Brady *573
Toolroom conveniences. (Ref. Book Sheet) 901, *1017
Tungsten - carbide, German practice with, Dr. George Schlesinger, 37; Discussion. C. G. Crowley 862
Tungsten-carbide tipped "Bull Dog." *951
Types of commercial plumb bobs. (Ref. Book Sheet) 787
With centrifugal feed. P. H. White .. 748
Wrench, rotary pneumatic, "Thor" No. 278 ..... *951
Wrench that will not mar the work. S. Wolff 1014
Tools. See also Dies and names of individual tools.
"Torit" Type 8-k kerosene burner *1023
Tractors, production of caterpillar parts for. Frank W. Curtis *1029

Trade Schools:

Southern school shop duplicates industrial conditions. Louis Greet *196
Training successors to a genius (ed) 216

Transmission:

Multi-speed, wise *379
Variable-speed, Morton *1061
Trent electrically-heated molding platens .. *722
Trimmers, bolt head. Fred R. Daniels *427

Trucks:

Generator, oxweld acetylene *220
Industrial, multiplies manpower *274
Lewis-Shepard "Footlift," *951
Present practice and trends in truck design. B. B. Bachman (Paper at World Engineering Congress) 825
Welded die and tool. Pollard *908
Tungsten-carbide cutting metal, "Dimondite" 683
Tungsten-carbide tool, German practice with. Dr. George Schlesinger ..... ‡*37
Turning with shallow cuts at high speeds. H. J. French and T. G. Digges 935
Tuthill Models, MS, RS, CS, lubricant pumps *457

U

U. S. Electrical Mfg. Co. "Uniclosed" motors *337

V

Vacations with pay, effect of (ed) 70
Vacuum cleaners, manufacture of, in Siemens-Schuckert Works. Dr. Hubert Dransfeld *923

Valves:

Lightening piston. W. P. Lambert ... ‡260
Ross improved operating *1063
Van Dorn 7-in. bench grinder *868
Ventilating unit, Paasche type F532 "Explosion proof" *1020
Vertical automatic, Pratt & Whitney, No. 2 six-station *867
Vise "Simplex," pipe *304
Vise, swivel backjaw, "Simplex" *913

W

Wadsworth No. 1 core-cutting and coning machine *606
Wadsworth No. 1 core-making machine ... *566

Wages:

Bonus system that failed. P. H. Bryant, 21; Discussion. Tom H. Blair, 270; R. E. Knox, 550; W. N. Brand, 653; C. A. Clarke 846
Wall chart of drills and tap sizes, "National" 724
Washing of small metal parts, large scale. Fred H. Colvin *665

Page

Waste:

Recovery of, from babbitting. P. J. Potter (Abstract of paper at A.I.M.M.E.) 584
Reduction at Westinghouse. C. B. Auel *1011
War on, at Oakland motor plant saves $542,000. Ray Chalmers *305

Welders:

Double-roller, heavy-duty, Thomson Model 375 ..... *330
Dual drive, unit, Westinghouse *872
Gas-engine driven, Lincoln *380
Gibb barrel-welding equipment *793
Idling device for "Stable Arc," Lincoln 1063
Improved Lincoln "Stable-Arc" *35
Motor-driven butt, Thomson special No. 12 ..... *71
Spot, Thomson Series 180 ..... *73
Vertical, power driven, Thomson Model 290 ..... *299
Weldomatic, outfit, Westinghouse *417

Welding:

And spinning, heavy gage aluminum kettle *22
Arc welding monorail conveyor. Joseph W. Meadowcroft *356
At Watertown Arsenal. Major J. B. Rose 543
Crosshead guides. Frank J. Oliver, Jr. *941
Efficiency of a welded joint. (Ref. Book Sheet) 1055
How, affects the design of a motor. Frank C. Hudson *831
Instruction, in technical school. E. L. Lucas *13
Insuring weld reliability by testing. Paul Orr ..... ‡*329
One-piece welded automobile body (Dodge Six) 983

Welding Equipment:

Electrode holder, General Electric Co. *186
Electrode, Lincoln "New Kathode" ... 222
Electrode pressure meter, Gibb *868
Rod, "Hascrome" 219
Rod, "Raco" packaged *605
Rod, "Weldite" Type S 909

Westinghouse:

Drum controller, Type A *185
Linestarter, dust-tight *418, *989
Super-centrifuge and filter press oil purifier *1060
Waste reduction at. C. B. Auel *1011
Welding unit, dual drive *872
Weldomatic outfit 417
"Whirlwind" bench-type horizontal drilling machine *1024
Whiting electric locomotive mover *719
Whitney No. 17 punch, and No. 49 notcher *913
Whitney T-iron bench legs and benches .. *1027
Wiesman improved safety guards for punch presses *795
Williams-White improved series punch presses *186
Wilson-Maeulen Model 8201 potentiometer-type recording pyrometer *870
Wise multi-speed transmissions *379
Wodack ¾-inch electric drill *303
Work (ed) 1056
Work handling devices bring approach to ideal automatic grinding. J. E. Caster *325

World Engineering Congress:

Japanese students at the (ed) 946
Twenty-six countries represented at .. 838a
Wrapper, "No-Ox-Id" protective 723

X

X-Ray:

Radiography as a tool in the metal industry. W. L. Fink and R. S. Archer *409

Z

Zeppelin, Graf, and public opinion (ed) ... 416

(*) Illustrated (‡) Diagram (ed) Editorial

AUTHORS' INDEX

ADDISON, THOMAS. Flanged motor mountings on foreign machine tools. *611
A'Hearn, F. M. Supplying materials on time through advance planning. (Abstract of paper at I.R.G.F.A.) .. 671
Ainsworth, A. W. Men over forty-five. Discussion 157
Alexander, John. Keeping posted on new tools 205
Alexander, R. S. Belts, foremen and paper work 16
Radio in the shop 406
Should workers buy company stock .. 555
Archer, R. S., Radiography as a tool in the metal industry *409
as a tool in the metal industry ... *409
Ashton, H. S. Before the days of blueprints 248
Auel, C. B. Waste reduction at Westinghouse *1011
Austin, Dwight E. Motorcoach design requirements 960

BACHMAN, B. B. Present practice and trends in truck design. (From paper at World Engineering Congress) ... 825
Baeslack, G. A. Tempering general purpose tools 663
Balch, E. P. Aluminum screens, designs for severe service *811
Ball, Martin H. Design changes that influence sales 240
Head for interchangeable, formed cutters ..... ‡67
Balla, John. Tempering general purpose tools 859
Beach, Fred S. Who should design patterns? 815
Beard, Theodore H. Dictation machines—a study in intricate mechanism *954
Becerril, Fausto. Radio in the shop 896
Becker, A. Fixture with equalizing clamps. ‡599
Behen, E. S. Equipment for the car repair shop. (Abstract of paper at A.R.T. F.A.) 545
Belbes, George. Does a highly developed system pay? 1039
Bell, J. What is modernization? 350
Going over the super's head 16
Placing the worker in the right job .. 587
Bellezza, R. G. Universal parts for sales and service simplification *976
Bermann, Franz. Discouraging rush orders 311
Belts, foremen and paper work 281
Man who shows interest 664
Novel reward for shop improvements 580
Oil cups or force feed 555
Selective casehardening of locomotive parts ..... ‡673
Best, C. H. Twelve years' experience with economic production quantities 940
Bexton, George. Pneumatic dolly for flexible staybolts *943
Bilgen, Henry E. Should the workman share responsibility? 1045
Who should design patterns? 431
Black, A. J. What is a slot?—Discussion 63
Blair, Tom H. Wage bonus system that failed. Discussion 270
Blamphin, A. Merrick. Novel reward for shop improvements 159
Bolton, J. W. Classification of gray iron alloys 53
Bonsall, Trevor. Chart board for the storeroom.—Discussion 553
Boone, Roscoe B. Trammel attachments for vernier calipers ..... ‡369
Boston, O. W. Power required to drill cast iron and steel 939
Bowne, N. J. Novel reward for shop improvements 311
Braasch, Herbert. Recent cases in engineering and patent law 354
Bradford, D. Milling fixture with equalizing clamps 68
Brady, George S. Heat-treating in a model small plant *991
Mechanical handling of screw-machine parts *175
Progress in materials, at the Metals Exposition *551
Tool work on contract *573
Brah, S. M. What should we teach apprentices? 657
Bramwell, Arthur. Keeping posted on new tools 55
Should we buy tools by the pound? 281
Brand, W. N. Wage bonus system that failed.—Discussion 653
Brewer, Allen F. Lubricating mechanisms *421
Oil filtration on machine tools *165
Brill, Peter A. Buying or making special tools 743
What obsolete equipment costs.—Discussion 331
Browett, Frank—Letting a big order go elsewhere 15
Brown, C. V. Should the workman share responsibility? 931
Brown, H. Oil cups or force feed 591
Brown, L. O. Cash or royalty on machines? 311
Discouraging rush orders 350
Getting men from other industries ... 48
Going over the super's head 170
Handicapping salesmen with wrong information 273
Hiring back old men first 845
Hiring men from other shops 539
Holland suggest an engineering council 771
Letting a big order go elsewhere 56
Man who shows interest 664
Net results—not first costs 195
Oil cups or force feed 591
Overtime vs. a longer working day... 579
Paying a bonus for temporary work.. 555
Reporting minor accidents 705
Should we buy tools by the pound? 15
Should workers buy company stock? 361
Spending production savings on sales 731
Stirring up the foreman on accidents.. 406
What is a slot?—Discussion 324
What is modernization? 697
Why some tools fail 859
Brown, N. E. Who should design patterns? 431
Brown, W. W. Mycalex—a machinable insulation 963
Browne, J. S. Flush pin gage for production inspection ..... ‡560
Handling bar stock and sheet metal.. *1053
Bryant, P. H. Wage bonus system that failed 21
Buchanan, W. J. Torch-cutting steel parts to replace castings. (Abstract of paper at A.W.S.) 544
Buckingham, Earle. German and Skoda tolerances compared. —Discussion .. 24
Quality control and production gages 937
Buettner, R. W. Reaming a curved hole.. ‡66
Burlingame, Luther D. Safety devices for machinery 638
Burnham, H. J. Committees for definite shop problems 783
Keeping posted on new tools 321
Paying a bonus for temporary work.. 860
Picking men in cheerful surroundings 405
Should workers buy company stock? 743
Stirring up the foreman on accidents. 556
Burton, C. F. S. Design changes that influence sales 432

CAHILL, LOUIS J. Spacing lights for shop illumination *277
Candee, Allan H. Gear geometry ..... ‡17, ‡57
Card, H. C. Boring a curved hole 673
Carey, R. F. What should we teach apprentices? 999
Carter, Frederick E. Platinum group metals in product design *822
Cassidy, P. F. Oil and grease, when and where each should be used 927
Caster, J. E. Work-handling devices bring approach to ideal automatic grinding. *325
Chalmers, Ray. War on waste saves $542,000 at Oakland motor plant. *305
Charles, R. M. Milling steering knuckles. ‡333
Chase, Herbert. Centralized lubricating systems *801
New automotive products at the National Metal Show *593
Flanged motor mountings on foreign machine tools *611
Clarke, C. A. Wage bonus system that failed. Bryant 21. Discussion 846
Clarke, Sydney E. Reporting minor accidents 744
Coates, C. B. High-frequency motors for portable tools 450
Colvin, Fred H. Accurate heat-treating in the small shop *877
Care and cleanliness, real assets in polishing *847
Centralized control of heat-treatment processes ..... ‡*161, 207
Connecting rod methods that are unusual *25
Do we need thirty eight tapers? 831
Keeping parts readily accessible 878
Large-scale washing of small metal parts *665
New alloys in railway rolling stock.. *449
Summing up the World Engineering Congress at Tokyo 952a
Condit, K. H. Industrial New England points the way *1009
Conroy, Tom. Reporting minor injuries .. 282
Coombs, Gilbert B. Gib-key puller. Discussion 1053
Coon, L. Circle cutter for paper templets. *944
Method of cross sectioning ..... ‡259
Cornelius, James R. Forging and machining a heavy crankshaft ..... ‡745
Visualizing the stresses in gearing 288
When do automatic machines pay? ... 859
Why some tools fail 1007
Crawford, Herbert F. Assembling chains for tractor treads *295
Facing bearings with an air drill.... *598
Crowley, C. G. German practice with tungsten-carbide tools. Discussion. 862
Curtis, Frank W. Automatic methods applied to grinding *585
Dies and tools for four-piece rear axle housings *915
Forging tools for rod bushings *549
Milling fixture designs that save time. *849
Production in the job shop *61
Production of track parts for caterpillar tractors *1029
Servicing floating bushings for connecting rods *323
Set-ups for Plymouth crankshafts .. *767
Straight-line production of rear axle housings ..... ‡*351

DANIEL, TREVOR F. Two methods of calculating depreciation 702
Daniels, Fred R. Relief attachment for cold-heading bolts *597
Twenty-year evolution in bolt head trimmers *427
Dapprich, C.E.L. Adjustable-speed d.c. vs. multi-speed a.c. motors, for machine tools *633
Darling, Herbert M. Committees for definite shop problems 361
An efficient tapping fixture..... ‡600
Factors that increase reamer life 12
Keeping posted on new tools 783
Stirring up the foreman on accidents. 169
Thread rolling in the screw machine. ‡559
Davis, Robert M. Metal working industry, third quarter, 1929 ..... 304b
DeLeeuw, A. L. Hydraulic feeds and speeds. (Abstract from World Congress paper) 774
Dennison, P. G. Safety guard for punch-press treadles 181
Denst, Leonard R. Cutter for washout-plug holes *1015
Detzer, R. N. Enameling stove parts in the modern manner *1047
Digges, T. G. Turning with shallow cuts at high speeds. (Abstract of paper at A.S.M.E.) 935
Dinger, Carl. M. Gib-key puller. Discussion. 1054
Dix, E. H. Service characteristics of light alloys *441
Doescher, Charles. Accurate scribe block for toolmakers ..... ‡332
Donner, Wm. H. Picking men in cheerful surroundings 169
Doris, R. L. Paying a bonus for temporary work 860
Dowd, B. J. Design changes that influence sales 239
Dransfeld, Dr. Hubert. Vacuum cleaner manufacture in the Siemens-Schuckert works *923
DuBrul, Ernest F. Some curious notions about the machinery industry 557
Dunham, George W. When sales take a slump 815

EBERHARDT, H. EZRA. Indicating "up" and "down" on hoists 390
Eckhard, Karl A. Wanted—satisfactory tests for cadmium plating 995
Eidmann, F. L. Mechanical engineering teachers hold summer session at Purdue 226b
Elder, Robert F. Reducing the costs of distribution 179
Ellis, O. W. Study of tin-base bearings. 1003
Ellsworth, A. C. Hardness distribution produced by cold working. (Abstract of paper at A.S.S.T.) 547
Evans, G. B. Design changes that influence sales 240

FADER, E. H. Device for controlling movements of threading tools .... ‡32
Fairall, E. L. Interesting men in the job. 350
What you do or what you get done?.. 1007
Faulhaber, Frank V. Keeping a line on tools 840
Felix, Edgar H. Photo-electric cell a mechanical selective device *819
Feltner, George H. Attachment for relieving printing-press cylinders *66
Quick-lift cams for jigs and fixtures .. ‡30
Fetter, Arthur. Centering eccentric work accurately 293
Feucht, Albert. Boring-bar holder for the lathe ..... ‡293
Fiedler, H. F. Special toolholders for planer ..... ‡333
Findlayson, F. E. Sheath wire—a new product for heating elements *445
Fink, W. L. Radiography as a tool in the metal industry 409
Firnhaber, Fred A. Spline milling spindle design *961
Fischer, W. E. Should we buy tools by the pound? 663
Fletcher, C. Norman. Cash or royalty on machines? 195
Getting men from other industries 160
Handicapping salesmen with wrong information 312
Spending production saving on sales .. 580
Flynn, Francis N. Reclaiming non-ferrous scrap metals. (Abstract of paper at A.I.M.M.E.) 546
Flynn, M. H. Design changes that influence sales 239
Executive considerations in tool design and production ..... ‡*313
Foldvary, Ernest. Progressive forming punch and die *1052
Self-locking mandrel *1016
Slitting die ..... ‡559
Forbes, A. W. Bonus for the ambitious.. 859
Design changes that influence sales.. 432
Indifference to the apprentice system. Discussion 178
Frank, Thomas B Accounting for depreciation in a period of falling prices .. 879
Franklin, Chester H. Turning crankpins in place *695

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Franklin, Henry C. Cutting radio tube filaments *369
Paying for dependability 555
Frederick, Arthur. Belts, foremen and paper work 206
French, Clifford H. Boring and turning simultaneously *1014
Design changes that influence sales ... 240
Rocking-cam driven punch for radial holes *747
French, H. J. Hot solutions for quenching steels 413
Turning with shallow cuts at high speeds. (Abstract of paper at A.S.M.E.) 935
Fruncillo, Arthur. Handicapping salesmen with wrong information 7
Fry, Lawford H. Locomotive forgings ... 411

GAILLARD, JOHN. Limit gaging—can an international system be adopted? 153, 197, 285
Gilder, Van. Keeping electric cords off the floor 333
Goddard, John. Who should design patterns? 619
Gordon, Bruce. Should workers buy company stock? 406
Goslar, Harry A. Paying for dependability. 1045
Graham, R. G. Committees for definite shop problems 205
Man who shows interest 591
Record cards tell the story 579
Reporting minor accidents 322
Greely, F. F. Painting safety guards in red. 13
Greenhalf, H. Buying or making special tools 1045
When do automatics pay? 931
Greet, Loui. Southern school shop that duplicates industrial conditions ... *196
Greetham, George A. Is the toolroom passing? 917
Paying a bonus for temporary work .. 783
Griffith, E. Hard and half-hard dies *1013
Training future diemakers 1032
Groom, J. H. Method for checking drawings. Discussion 258
Guernsey, Charles O. Design of rail motor cars *973
Gunn, G. H. Reducing the scrap heap 311
Gustof, Stanley J. Re-hiring old employees. 16
Guyler, A. F. Stirring up the foreman on accidents 556

HAGEMANN, GEORGE E. Modernizing the factory handling system *852
Hagen, Peter. Emergency method of thread calculation 632
Modernizing the checking squad 824
Scale for unscalable drawings *983
Hamill, T. E. Hot solutions for quenching steels 413
Hamilton, S. E. Should we buy tools by the pound? 281
Hamilton, William E. Developing new products 967
Hammitt, Don R. Laying out an angle without a protractor 984
Method of dividing by the use of a scale ..... ‡644
Hampson, Donald A. Kink in fitting roller bearings ..... ‡31
Manufacture of draftsmen's scales ... 316
Hardecker, John F. Co-operation between drafting room and shop.—Discussion 193
Design changes that influence sales .. 239
Friendliness in business 697
Hiring men from other shops 47
Inspectors for the shop—why not for draftsmen.—Discussion 27
Metals in aircraft construction *629
Neglecting letters loses an order 771
Tempering general purpose tools 932
Hargrave, T. H. Keeping posted on new tools 205
Harvey, W. G. Magnesium and its alloys . 624
Haselgrove, R. L. Hiring men from other shops 579
Overtime vs. a longer working day ... 349
What shall we teach apprentices? ... 1040
When do automatic machines pay? .. 1046
Heckman, Paul S. Do automatic machines always pay? 579
Henderson, James. Problem in shaper work ..... ‡294
Henderson, Jim. Repairing a broken crankshaft ..... ‡370
Henry, C. F. Clamp for splicing cable-eyes *1053
Henry, C. L. Al and Ed agree on obsolescence 592
Improvement in grinder collars.—Discussion ..... ‡643
Henry, Charles F. Design changes that influence sales 240
Finishing connecting rods and valve tappet guides *712
Gage for setting brake lever arms .. *673
Henson, Henry H. Devices for handling driving-wheel tires *900
Extractor for stems of piston valves .. 182
Indexing mandrel for main-rod brasses. *863
Portable furnace for melting brass .. *899
Herr, Homer A. Should workers buy company stock? 932
Herrick, E. D. Who should design patterns? 431
Hewitt, R. G. Congestion at the machine tools. Discussion 210
Small-shop foreman as personnel man. —Discussion 661
Stirring up the foremen on accidents.. 556
Hill, Rawland L. Rack for heavy stock .. ‡598
Hobbs, T. W. Should the workman share responsibility? 1007

Page

Hoistington, Harry. Dimension lines on drawing 250
Homewood, J. Going over the super's head. 55
Hook, Ira T. Welding copper and high-copper alloys. (Abstract of paper at A.W.S.) 595
Hopkins, P. W. Porcelain enameling metal parts *49
Hudson, Frank C. How welding affects the design of a motor *831
New design that is old *444
Hunt, E. J. Progressive enameling of the Plymouth fender *267
Hyde, Frank A. Committees for definite shop problems 321
Keeping posted on new tools 281
Oil cups or force feed? 362
Reporting minor accidents 169
Hyler, John E. Section lining device ..... ‡559

INGLERIGHT, F. L. Tempering general purpose tools. 1045
Upsetting production schedules 999
Irmer, Charles B. Fixture for rolling pins. ‡293
Roller for flanging tubes ..... ‡370
Salesmanship from the viewpoint of a purchasing agent 1050
Iveson, A. E. Production methods in the railroad shop. (Abstract of paper at the I.R.G.F.A.) 672

JAMES, GORTON. Wanted—an obsolescence insurance company 839
James, H. Cash or royalty on machines .. 273
Going over the super's head 170
Insuring machines against undue wear. 1039
Interesting men in the job 771
Overtime vs. a longer working day ... 539
Radio in the shop 783
Rewards for suggestions 349
Spending production savings on sales. 657
Tom Johnson has a plan to reduce unemployment.—Discussion 180
Who should design patterns? 967
James, H. D. Co-operation in engineering. 448
Johnson, Forrest L. Unusual indexing jig. 1013
Johnstone, R. E. Heat-treatment of airplane parts *389
Metal work in building airplanes ... *699
Jones, J. T. Equipment for the car repair shop. (Abstract of paper at A.R.T.F.A.) 545
Jones, L. B. Keeping posted on new tools. 15
Paying a bonus for temporary work. 361
Jordan, E. J. Convex facing in a lathe ... ‡372
Measuring within 0.004 in. with a transit.—Discussion 786

KAMPMEIR, FREDERICK. Rewards for suggestions 7
Karelitz, G. B. Study of tin-base bearing metals 1003
Kasper, R. H. Picking men in cheerful surroundings 405
Preventing damage to a lathe 674
Replacing endless belts 558
Wire gages again.—Discussion 287
Kauffman, Samuel. Aid to checkers ..... ‡643
Entertaining—and how much? 1040
Multi-blade screwdriver *864
Kaufman, Harry. Best defense against communists.—Discussion 164
Bonus for the ambitious 1046
Committees for definite shop problems. 859
Design changes that influence sales .. 432
Getting workers to obey rules 388
Interesting men in the job 657
Making good use of the cost system .. 156
Man who shows interest 664
Personnel and production.—Discussion. 694
Radio in the shop 205
Reducing the scrap heap 47
Should workers buy company stock? 895
Spending production savings on sales. 580
What is modernization? 195
Why some tools fail 705
Kaufmann, N. Repairing a chuck *1054
Kentish-Rankin, I. L. How about lights for next winter?—Discussion 740
Kenyon, G. K. Games at the noon hour .. 591
Kerr, George T. Seven-stage progressive die *1051
Kerr, T. Why some tools fail 895
Kimball, Dexter S. Ancient manufacturing. *922
Kirkbride, Charles E. Developing new products 968
Kirkbride, Charles H. Jr. Buying or making special tools 931
Should the workman share responsibility? 895
Kirkpatrick, W. W. Going over the super's head 55
Klein, Dr. Julius. American branch factories abroad 688
Klingstein, Fred. Man who shows interest. 406
Klyne, Charles. Does a highly developed system pay? 845
Knox, Rupert E. Wage bonus system that failed.—Discussion *550
Kollarik, J. Stirring up foremen on accidents 362
Kornschutz, Edward. Effective pinion puller ..... ‡372
Equipment in a Southern railroad shop *736
Simple tools for babbitting and boring connecting rods ..... ‡30
Kruger, Theodore. Holder for collets ..... ‡260
Using blind "ads" 862
Kugler, Charles. Attachment for convex facing ..... ‡712
Eliminating pins for locating purposes ..... ‡644
Making brass disks.—Discussion 296

Page

Repairing T-slots in toolblocks 900
Tools for cutting wood and fiber .... ‡371
What should we teach apprentices? ... 845
Kunz, William F. Draftsman learns a lesson in the shop 444
Practical contact for the designer 246
Kupper, Harry. Should workers buy company stock? 783
Standardising drawing sizes 425
Kupper, S. Put salvage up to a committee 210

LADWIG, FRED. Holding irregular shaped disks in a lathe chuck ..... ‡674
Laib, Ernest E. Stirring up the foremen on accidents 592
Lambert, P. W. Cored crown brasses *832
Lightening piston valves 260
Lederc, M. N. Who should design patterns? 967
Lee, Edward C. Chrysler hydraulic brakes, their design and tools for producing *171. *201
Leo, Paul. Home-made mandrel press .... ‡296
Leonard, H. P. Gage simplifies setting of drill jigs *786
Safety kink for storing plates *1054
Lincoln, W. B., Jr. Learning from the small shop 1007
Lord, C. B. Good housekeeping in a railroad storeroom *43
Loveland, R. B. Convenient cabinet for the gear hobber *1013
Improvised swaging machine *371
Portable miller for pedestal toes *295
Lowry, E. J. High strength cast iron 412
Lucas, Ernest L. Welding instruction in a technical school *13
Luerasen, G. V. Behavior of carbon tool steel on quenching 407

McCORMACK, BERNARD F. Games at the noon hour 1045
McCullough, P. J. Piston leak gage for pneumatic hammers *451
MacLean, B. H. E. Boring a curved hole. 182
Malliet, W. H. Material economy in sheet metal blanking ..... ‡189
Maplethorpe, H. Keeping posted on new tools 362
Man who shows interest 321
Reducing the scrap heap 657
Rewards for suggestions 349
Should we buy tools by the pound? .. 281
Stirring up the foreman on accidents. 705
What shall we teach apprentices? 883
Mardy, W. Methods of checking drawings —Discussion 425
Marion, Homer. Drilling a curved hole ... *899
Markey, L. E. Can shop losses be charged to sales? 7
Going over the super's head 56
Rewards for suggestions 312
When do automatic machines pay? . 895
Marks, R. E. Air-operated tools in a railroad shop *1052
Safety guard for cold chisel *748
Split dies for press work *784
Martinsen, G. C. Reducing the scrap heap 311
Masek, John A. Who should design patterns? 815
Matter, James K. Entertaining—and how much? 1039
May, John Mark. Hiring men from other shops 160
Mayoh, F. H. Twin-unit machines for multiple production *289
Meadowcroft, Joseph W. Arc welding a monorail conveyor *356
Messler, Allen H. Design changes that influence sales 431
Michener, C. D. Improvised hydraulic carriage return *711
Millar, E. Picking men in cheerful surroundings 405
Moore, H. Cutting spiral grooves in thrust washers ..... ‡334
Moran, John S. Night shift 1039
Morgan, H. W. Universal reaming fixture for connecting rods ..... ‡334
Morrison, C. J. Does a highly developed system pay? 697
Rewards for suggestions 159
Mumper, Arthur. Changing over from jobbing to production methods ..... ‡746
Small-shop foreman as personnel man 52
Munn, H. Q. Angle dresser for abrasive wheels ..... ‡710

NADON, C. L. Emergency repair ..... ‡31
Nealy, J. B. Heat-treating aircraft engine bearings *1041
Needham, W. R. Blackboard in the drafting room. Discussion 983
Give the draftsman a chance. Discussion 258
Indifference to the apprentice system. Discussion 667
Interesting men in the job 697
Laying out angles without a protractor ..... ‡643
Man who shows interest 706
Picking men in cheerful surroundings. 282
Taking on a sideline 160
Nielsen, Sigurd C. Ed and Al agree on obsolescence 169
Nixon, K. H. Keeping posted on new tools 55

O'BRIEN, Arthur V. Tools for small-lot production of brass parts *659
Oliver, Frank J., Jr. Block simplifies cold riveting 943
Boring a tapered hole in a locomotive crosshead *785
Crosshead slipper practice at the C. & N. W. shops *941

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Driving pin used in a lathe.....*864
Small machine tools applied to instrument manufacture .....‡*343, *581
Small meter gears.....*841
Steering knuckle production at the Studebaker plant *725
Studebaker methods of forging and heat-treating .....‡*383
Orr, Paul. Insuring weld reliability by testing welders .....‡*329
Owens, W. J. Bonus for the ambitious...1008
Buying or making special tools.....1045
Developing new products.....967
Insuring machines against undue wear 731
Interesting men in the job..... 350
Neglecting letters loses an order..... 580
Paying a bonus for temporary work. 663
Reducing the scrap heap..... 273
Rewards for suggestions..... 7
Should workers buy company stock?.. 205
Stirring up the foremen on accidents. 556
Oxford, C. J. Power required to drill cast iron and steel..... 939

PARKER, ARTHUR F. Cutting internal threads in tough metals ..... ‡32
Holder for collets. Discussion..... 863
Parkhurst, Douglas L. Who should design patterns? 967
Parkhurst, Malcolm K. End mill used as boring tool *1015
Spring flexible coupling.....*832
Paton, J. Discouraging rush orders..... 48
Peach, W. H. Cutting cams in a radial drill .....‡295
Peterson, Roy E. Blackboard in the drafting room 259
Method of cross sectioning.....‡644
Porter, Charles Talbot. Design factors of commercial airplanes 975
Potter, J. A. Co-operation between drafting room and shop. Discussion.... 45
Co-operation between drafting room and shop. Discussion..... 978
Design changes that influence sales... 239
Executive routine of a modern drafting room. Discussion 813
Inspectors for the shop, why not for draftsmen. Discussion 27
Who should design patterns?..... 619
Potter, P. J. Recovery of waste from babbitting. (Abstract of paper at A.I.M.M.E.) 584

RANDALL, H. D. Design of textolite gears *1033
Molded products that replace metals *251, *639
Rankin, K. Art of hiring men.....1049
Ranney, C. R. Tools for "Hartometer" production *1001
Raymond, Fairfield E. Controlling manufacture by economic lot sizes. (Abstract of paper at S.A.E.)..... 669
Redden, Hubert E. Deep-hole drilling job. *283
Reesey, Charles M. Milling operations on Houdaille shock absorbers.....*271
Reichert, G. Equipment for the car repair shop. (Abstract of paper at A.R.T.F.A.) 545
Rich, I. B. Three-piece wedging key.....‡259
Two hydraulic presses for railroad shop use *711
Richard, N. C. Radio in the shop..... 321
Ripley, P. C. Underlying principles of soft soldering 365
Robinson, J. M. Redesign for welded construction *249
Rose, Major J. B. Welding at Watertown Arsenal. (Abstract of paper at A.W.S.) 543
Rowell, Wm. S. Better oiling on machine tools. Discussion 560

SANDMANN, WM. F. Jig plate with adjustable bushing bars..... ‡67
Sargent, Jack. Buying or making special tools 931
Paying a bonus for temporary work.. 55
Schaefer, A. E. Radio in the shop..... 663
Schaphorst, W. F. Cooling a hot bearing. 843
To detect hot bearings..... 583
Schinman, Carl E. Reducing the scrap heap 350
Tempering general purpose tools..... 932

Page

Schirmer, William. Committees for definite shop problems 706
Interesting men in the job..... 579
Paying for dependability.....1007
Schlesinger, Dr. George. German and Skoda tolerances compared 887
German practice with tungsten-carbide tools. gr..... *37
Schmidt, F. A. J.
Belts, foremen and paper work..... 169
Committees for definite shop problems. 744
Discouraging rush orders..... 159
Design changes that influence sales... 431
Ed and Al agree on obsolescence..... 281
Games at the noon hour..... 931
Handicapping salesmen with wrong information 195
Hiring men from other shops..... 921
Holland suggests an engineering council 539
Interesting men in the job..... 771
Keeping posted on new tools..... 206
Man who shows interest..... 361
Net results—not first costs..... 47
Novel reward for shop improvements. 845
Oil cups or force feed?..... 322
Radio in the shop..... 593
Rewards for suggestions..... 349
What is modernization?..... 731
What shall we teach apprentices?....1040
When do automatic machines pay?...1046
Who should design patterns?..... 619
Schwam, Morton. Design changes that influence sales 432
Practical contact for the designer. Discussion 617
Substitute for cross-hatching.....*810
Scott, Wirt S. Tempering and coloring axes *707
Seeds, A. Dana. Draft protractor for die-makers .....‡785
Faceplate square *1014
Servel, O. B. Repairing a bulldozer.....*784
Shafran, Philip F. Saving time in die design *944
Shaw, G. B. Rapid oiler for instrument bearings .....‡294
Shaw, R. A. Safe dies a necessity in power-press safety 741
Sherman, R. M. Design changes that influence sales 432
Simon, Henry. Design of the Zeiss Planetarium *227, *433, 625
Production operations on the Zeiss Planetarium *737, 897
Smith, Eli. Entertaining—and how much? 921
Soderberg, C. Richard. Factor of safety and working stress.....1000
Squibb, Lloyd Y. Executive routine of a modern drafting room..... 616
Stowell, L. C. Design of the dictaphone—part played by the engineer..... 953
Stryker, Ralph N. Buckets for handling steel shavings .....‡599
Man who shows interest..... 591
Paying a bonus for temporary work.. 743
Stirring up the foremen on accidents.. 895
Swenson, L. F. Committees for definite shop problems 896
Does a highly developed system pay? 883
Night shift 1039
Paying a bonus for temporary work.. 860
Radio in the shop..... 743
Should we buy tools by the pound?.. 56
When do automatics pay?..... 405
Sykes, W. E. 10,000 to 1 reduction motion *426
Sykes, W. P. Hardness distribution produced by cold working. (Abstract of paper at A.S.S.T.)..... 547

TABOR, W. H. Does a highly developed system pay? 921
Takahashi, K. Chart for selecting substitute for forging.....‡831
Finding clearance for work on boring mills 1016
Taub, Alex. Chevrolet-six design based on economics *241
Taylor, Floyd T. Economies with automatic plating equipment.....*535
Terrell, E. A. Controlling production costs in the small shop.....*649, 691, 733
Thompson, John T. Man who shows interest 321

Page

Tomney, Charles C. Jig for drilling drain holes in pistons.....‡370
Toulmin, Harry A., Jr. How patents fit into sales strategy..... 363
Tour, Sam. Aluminum alloys for pressure die castings 28
Towlson, J. T. Belts, foremen and paper work 206
Committees for definite shop problems 896
Cutting threads in tough metals. Discussion 944
Gear cutting on a shaper. Discussion. 747
Gib-key puller 674
Hiring men from other shops..... 657
Interesting men in the job..... 731
Keeping posted on new tools..... 406
Making gages to specified tolerances.. 766
The night shift..... 883
Overtime vs. a longer working day.. 349
Picking men in cheerful surroundings 361
Putting-on tool. Discussion.....1035
Reducing the scrap heap..... 539
Steel piston rings. Discussion..... 390
Tripp, G. W. What should we teach apprentices? 921
Twist, F. C. Buying or making special tools 1007

VAN DEVENTER, JOHN H. Trends in standardized quality production. (Abstract from paper at World Congress) 777
Van Horn, Victor H. Developing new products 968
Vandercook, D. D. Non-slipping lathe dog.*864

WAGNER, OTTO A. Precision attachment for lathes.....‡260
Wann, R. L. Reporting minor accidents.... 322
Warner, W. E. Games at the noon hour..1008
Warren, George C. Comparator for inside micrometers .....‡598
Wasbauer, Alfred. Shortening labor in design calculations .....‡617
Watkins, Robert. When do automatic machines pay? 1046
Watt, George F. Repairing drawing boards 644
Westbrook, M. H. Stirring up the foreman on accidents.....1008
Wheeler, H. L. Hand-operated fixture for winding conical springs..... ‡68
Knockout plug for a taper socket....‡293
Spherical counterbore .....‡371
Valve wheels for use on jigs and fixtures *900
White, Arnold C. Standardizing drawing sizes. Discussion 826
White, P. H. Keeping a live drawing file.. 628
Tool with centrifugal feed..... 748
Willey, Charles H. Bending fixture for terminals .....‡711
Bending small parts in a hand press.. ‡31
Buying or making special tools..... 927
Man who shows interest..... 706
Rivets vs. screws..... 259
Simple bending fixture.....*1051
Tight terminals for meters.....*984
Tool for piercing walls of ammeter cases .....‡332
Wire-bending fixture 181
Willey, O. C. Taking the machine to the work 181
Williams, O. G. Precision in a low-priced product *9
Wilson, Wilbur C. A bonus for the ambitious 743
Wise, William C. Reducing the scrap heap 159
Wood, Joseph Kaye. Conical spring design.‡620
Variable-pitch helical springs.....‡827
Wolff, S. Wrench that will not mar the work *1014
Wooton, Paul. Industrialization of Latin America seen in near future.....382d
Latin America looking for "last word" in industrial equipment.....226a
Wormwood, A. J. Repairing micrometers..‡599
Wright, D. C. Exchanging ideas on shop methods 999
Hiring men from other industries.... 273
Oil cups or force feed..... 555
Rewards for suggestions..... 312

YAPP, LEWIS J. Ed and Al agree on obsolescence 16
When sales take a slump..... 968

(*) Illustrated (‡) Diagram (ed) Editorial